

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2022

Submitted Date:

06/23/2022

Document Number:

701103239

FIELD INSPECTION FORMLoc ID 313159 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10724

Name of Operator: NORTH SHORE EXPLORATION AND PRODUCTION

Address: 105 EDGEVIEW DR SUITE 400

City: BROOMFIELD State: CO Zip: 80021

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hindle, Holly		holly@northshoreenergyllc.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264680	WELL	SI	11/01/2019	GW	081-07102	EVANS FEDERAL 22-28	SI

General Comment:

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

- No API # on well sign.
- No API # on battery sign. No public road used to access the Tank battery site
- Metal tank by meter shed and separator NFPA, contents, and capacity are faded.
- Deadman marker south west of well has been bent over.
- Weeds growing inside of tank battery berm and separator berm and around well.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Metal tank by meter shed and separator NFPA, contents, and capacity are faded.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/31/2022
Type	BATTERY		
Comment:	No API # on battery sign. no public road used to access the Tank battery site;		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/31/2022
Type	WELLHEAD		
Comment:	No API # on well signs.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/31/2022

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds growing inside of tank battery berm and separator berm and around well.		
Corrective Action:	Comply with Rule 606 (housekeeping) Comply with Rule 610 (Fire Hazards)	Date:	07/09/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	#		
Comment:	Deadman marker south west of well has been bent over.		

Corrective Action:	Install proper guy line markers per Rule 1003.a		Date:	07/09/2022
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	See housekeeping section. Weeds growing in berm.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		

Comment:		See housekeeping section. Weeds growing in berm.					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
METHANOL	1	<50 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
Paint							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth							
Comment:		See housekeeping section. Weeds growing in berm.					
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected FacilitiesFacility ID: 264680 Type: WELL API Number: 081-07102 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Form 4 Doc # 403056779

Corrective Action: _____

Date: _____

Flowline

#1	Type: Sales Line	of Lines
----	------------------	----------

Flowline DescriptionFlowline Type: Sales Line

Size: _____

Material: _____

Variance: _____

Age: _____

Contents: _____

Integrity Summary

Failures: _____

Spills: _____

Repairs Made: _____

Coatings: _____

H2S: _____

Cathodic Protection: _____

Pressure Testing

Witnessed: _____

Test Result: _____

Charted: _____

COGCC Rules (check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Witness flowline test from well to meter. Held steady 345 psi for 30 mins

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403088479	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787989
701103254	Inspection 701103239 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5787985