

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2022

Submitted Date:

07/08/2022

Document Number:

702500202

## FIELD INSPECTION FORM

 Loc ID 311897 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 10766  
 Name of Operator: ARKOMA OPERATIONS LLC  
 Address: 2121 S COLUMBIA AVE SUITE 101  
 City: TULSA State: OK Zip: 74114
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Price, Andrew	918-260-8324	aprice@arkomaops.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216577	WELL	PR	01/01/2020	GW	067-08183	FASSETT 1-A	PR
276638	WELL	PR	11/20/2005	CBM	067-09025	IGW 104	PR
290037	WELL	PR	06/09/2009	CBM	067-09347	IGW 120	PR
475909	Domestic Tap	AC	11/17/2020		-	Domestic Tap 7NWNE	AC

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment: Emergency contact: 800-452-1578  
Local emergency: 911

Corrective Action:

Date:

**Good Housekeeping:**

Type: OTHER

Comment: Lube oil at IGW 120 wellhead is impacting surface material (IMG 05).

Corrective Action: Remove oily residue and impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/23/2022

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Flow Line # 15

Comment: In use: 2 3" lines from pump jacks to separators, 2 2" lines from pump jack wellhead to gas powered prime mover, 2" line from plunger lift to separators, 4 2" lines from separators to produced water, 3 2" lines from gas meter run to off location.  
  
Out of use: 2 2" lines at IGW 120 separator, and 2" line at IGW 104 separator are not locked out/tagged out.

Corrective Action: Out of service flowlines must be tagged and identified per rule 1101.(3)

Date: 07/24/2022

Type: Pig Station # 3

Comment:

Corrective Action:

Date:

Type: Gas Meter Run # 3

Comment: Gas meter calibrations are within the last year.

Corrective Action:

Date:

Type: Vertical Heated Separator # 2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 2

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked # 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 3

Comment: Separator vent stacks are screened properly.

Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Gas powered		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry,		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		37.122341,-107.755039
Comment:	Produced water tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	40 bbl
Other (Type)	cone top

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Gravel and dirt earth berm.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		37.122844,-107.755000
Comment:	Produced water tank.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	cone top

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Dirt and gravel earth berm.</a>				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 216577 Type: WELL API Number: 067-08183 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 276638 Type: WELL API Number: 067-09025 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 290037 Type: WELL API Number: 067-09347 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 475909 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Compaction	Pass			
		Gravel	Pass			
Gravel	Pass					

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500203	photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798740">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798740</a>