

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/25/2022

Submitted Date:

08/28/2022

Document Number:

688313004

**FIELD INSPECTION FORM**
 Loc ID 479194 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10243

Name of Operator: GMT EXPLORATION COMPANY LLC

Address: 4949 S NIAGRA STREET STE 250

City: DENVER State: CO Zip: 80237

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Blair, Max	720-862-4503	mblair@gmtexploration.com	
Eberhardt, Whitney	303-586-9289	w.eberhardt@gmtexploration.com	Principal Agent
Cox, BJ	303-586-9274	bjcox@gmtexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480426	WELL	DG	06/02/2022		039-06722	Irwin 6-65 23-11 10HN	WO

**General Comment:**

Flowback Inspection

No bradenheads test (Form 17) seen in the COGCC database.

Production facility is under construction.

Poseidon tank is down.

**Inspected Facilities**Facility ID: 480426 Type: WELL API Number: 039-06722 Status: DG Insp. Status: WO**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Completion**Operation: FlowbackDate Flowback: 08/25/2022Contractor: BullseyeComment: One well flowing back: 7 frac tanks; 2 oil, 1 separator, 1 ECD not on. Only hot water (200 degrees F) and gas (going to gas sales line).

Tank labels and more high pressure line signs are on the way to location. Keep thief hatches closed.

Operator needs to submit a Form 17.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Silt Fences	Fail					

Comment: [See attached photo of silt/frog fence down below location. This is also a COA on the Form 2A.](#)

[Recent rain.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f\(2\)C.](#)

Date: 09/06/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403150507	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842603">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842603</a>
688313015	GMT Irwin 6-65 23-11 10 HN flowback	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842588">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842588</a>