

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/29/2022

Submitted Date:

08/29/2022

Document Number:

702500355**FIELD INSPECTION FORM**
 Loc ID 312052 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216500	WELL	PR	01/01/2003	CBM	067-08106	ANIMAS 34-10 36-1	PR
297003	WELL	PR	02/01/2011	CBM	067-09593	ANIMAS 34-10 36-1A	PR
297004	WELL	PR	05/01/2021	CBM	067-09594	ANIMAS 34-10 36-2A	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Lube oil at 1A wellhead has impacted surface material (IMG 03).

Corrective Action:

Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 09/13/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

OTHER

Comment:

Pump jacks and plunger lift wellhead are enclosed by stock panel.

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bird Protectors

# 1

Comment:

Separator vent stack is screened properly.

Corrective Action:

Date:

Type: Other

# 1

Comment:

Lube oil at 2A wellhead does not have spill prevention (IMG 04).

Corrective Action:

Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.

Date: 09/13/2022

Type: Gas Meter Run

# 3

Comment:

Gas meter calibrations are within the last year.

Corrective Action:

Date:

Type: Bradenhead

# 3

Comment:

Bradenheads are accessible.

Corrective Action:

Date:

Type: Compressor

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 4

Comment:	Telemetry, solar panels, cathodic protection, valve pit			
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 3			
Comment:				
Corrective Action:			Date:	
Type: Prime Mover	# 2			
Comment:	Gas powered prime mover			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 8			
Comment:				
Corrective Action:			Date:	
Type: Flow Line	# 7			
Comment:	3 4" lines from wellheads to separators, 2 1" lines from separator to gas powered prime movers, line from separator to produced water off location, 1" line from separator to plunger lift wellhead is out of service and is locked out tagged out.			
Corrective Action:			Date:	
Type: Pump Jack	# 2			
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities			
Facility ID: <u>216500</u>	Type: <u>WELL</u>	API Number: <u>067-08106</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:			
Corrective Action:		Date:	
Facility ID: <u>297003</u>	Type: <u>WELL</u>	API Number: <u>067-09593</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:			
Corrective Action:		Date:	
Facility ID: <u>297004</u>	Type: <u>WELL</u>	API Number: <u>067-09594</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass					
Gravel	Pass					
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403150318	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842399">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842399</a>
702500356	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842393">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842393</a>