

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2022

Submitted Date:

08/29/2022

Document Number:

702500359**FIELD INSPECTION FORM**Loc ID 312068 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		regulatory@logosresourcesllc.com	All SW field inspections
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	All SW field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216555	WELL	PR	07/01/2019	GW	067-08161	BONDAD 33-9 13A	PR
267414	WELL	PR	04/18/2003	CBM	067-08794	CLOVIS A 2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused 4" pipe at produced water tank (IMG 03), and unused 2" pipe on south edge of location (IMG 04).		
Corrective Action:	Return all unused equipment to service or store off location per rule 606.		Date: 09/13/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Produced water tank is enclosed by wire fencing		
Corrective Action:			Date:

Equipment:

			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:	2" line from wellhead to separator, 3" line from gas meter run to off location. 1" line from separator to wellhead is locked out tagged out.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Telemetry, cathodic protection,		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	separator vent stack is screened properly		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		PBV STEEL		37.129436,-107.870630	
Comment:	Partially buried produced water tank with steel mesh top.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	125 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	216555	Type:	WELL	API Number:	067-08161	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	267414	Type:	WELL	API Number:	067-08794	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Berms	Pass					
Ditches	Pass					
Rip Rap	Pass					
		Gravel	Pass			
Gravel	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403150321	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842401
702500360	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842395