

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/30/2022

Submitted Date:

08/30/2022

Document Number:

702500367

FIELD INSPECTION FORM

Loc ID 311965 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216476	WELL	PR	08/12/1997	CBM	067-08082	T.H. 32-7 12-1	PR
290382	WELL	PR	11/09/2007	CBM	067-09361	TIFFANY 32-7-12 8	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Lube oil at pump jack has begun to impact surface material (IMG 05).		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	2 pieces of 2" pipe and several wood boards are debris (IMG 07).		
Corrective Action:	Remove debris per rule 606.	Date:	09/07/2022
Type	UNUSED EQUIPMENT		
Comment:	Exhaust muffler at pump jack is not in use (IMG 04).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.	Date:	09/14/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pump jack and wellhead enclosed by metal fencing.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Bird Protectors	# 2		
Comment:	Separator vent stacks are screened properly.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry, valve cluster pit		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible		
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	Gas powered		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 8		
Comment:	4" and 3" line from plunger lift wellhead to separator, 3" line from pump jack wellhead to separator, 3 2" lines from separators to produced water off location, 4" line from separators to off location, 1 1" line from separator to gas powered prime mover.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibrations are within the last year.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:	Rig anchors are not marked properly (IMG 03).		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	09/14/2022

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216476 Type: WELL API Number: 067-08082 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 290382 Type: WELL API Number: 067-09361 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					
		Gravel	Pass			
				Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Landowner appears to be storing agricultural equipment on west edge of location (IMG 06).	klinka	08/30/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403152222	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844206
702500368	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844204