

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAGNALL-66S92W /34NWSW

Location ID: 334916



Photo #8238 From entrance to location.



Photo #8239 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAGNALL-66S92W /34NWSW

Location ID: 334916



Photo #8240 From entrance to location.




Photo #8245 Stained soils.

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAGNALL-66S92W /34NWSW

Location ID: 334916



Photo #8246 Stained soils by separators.



Photo #8241 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAGNALL-66S92W /34NWSW

Location ID: 334916



Photo #8242 From entrance to location.



Photo #8247 Insufficient tracking control at entrance to location.