Inspector Name: Finkenbinder, Chane

FORM INSP

> Rev X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109





Inspection Date: 10/20/2022 Submitted Date:

Document Number: <u>700901255</u>

11/04/2022

## FIELD INSPECTION FORM

Loc ID Inspector Name:		me:	On-Site I	On-Site Inspection		Status Summary:  THIS IS A FOLLOW UP INSPECTION				
320290	Finkenbinder, Chane  or Information:  Operator Number:10459  of Operator: EXTRACTION OIL & 0  s:370 17TH STREET SUITE 520  DENVER State:		2A Doc Num:							
Operator In	formation:					X F	OLLOW UP INSPECTION F	REQUIRED		
OGCC Oper	rator Number:	10459				N	O FOLLOW UP INSPECTION	ON REQUIRED		
Name of Ope	erator: EXTRACT	TION OIL &	GAS INC		<u> </u>	<u>Findi</u>	ngs:			
						7	Number of Comments			
		00112 02				1	Number of Corrective Ac	tions		
City:	DENVER	State:	CO	Zip:8	0202	X Co	orrective Action Response Req	uested		
						P	NY CORRECTIVE ACTION REVIOUS INSPECTIONS T EEN ADDRESSED ARE S	THAT HAVE NOT		
Contact Info	ormation:									
Contact Name		Phon	e	Email		Comment				
,				Inspections (	@civiresources	s.co	All Inspections			
Inspected F	acilities:									
Facility ID	Туре	Status	Status Date	Well Clas	s API Num		Facility Name	Insp Status		
203370	WELL	SI	08/01/2017	GW	001-08879	9	KRAFT 34-14	SI		
General Cor	mment:									

Inspector Name: Finkenbinder, Chane

			<u>Location</u>		
Overall Good: 🔀					
Emergency Contact N	lumber:				
Comment:	Adequate				
Corrective Action:	Date:				
Good Housekeeping	<u>L</u>				
Туре	WEEDS				
Comment:					
Overall Good:					11/25/2022
Overall Good:					
Spills:					
Туре	Area	Volume			
Comment:	<u>· · · · · · · · · · · · · · · · · · · </u>				
Fencing/:					
Туре	LOCATION				
Comment:	Chainlink				
Corrective Action:				Date:	
Equipment:					corrective date
Type: Ancillary equipr	ment #	1			
Comment:					
Corrective Action:				Date:	
Type: Deadman # & N	Marked #	4			
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	#	1			
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	#	1			
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	#	1			
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heat	ted Separator #	1			
Comment:					
Corrective Action:				Date:	
	1				

Inspector Name: Finkenbinder, Chane Tanks and Berms: Contents Capacity Type Tank ID SE GPS CRUDE OIL **300 BBLS** STEEL AST 39.957484,-104.627902 Comment: Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms** Туре Capacity Permeability (Wall) Permeability (Base) Maintenance Earth Walls Sufficent Base Sufficient Adequate Adequate Comment: Corrective Action: Date: # SE GPS Contents Capacity Type Tank ID PRODUCED WATER <50 BBLS CONCRETE SUMP/VAULT Comment: Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms** Туре Capacity Permeability (Wall) Permeability (Base) Maintenance Earth Adequate Walls Sufficent Base Sufficient Adequate Comment: Date: Corrective Action: Wells Served By Facilities Above <u>AirsID</u> **API Number** API Number AirsID 001-08879 Venting: Yes/No NO Comment: Corrective Action: Date: <u>Flaring:</u>

Comment:

Corrective Action:

Type

Date:

Inspector Name: Finkenbinder, Chane		

	inkenbinder, Char	· <del>-</del>	Inspecte	d Facilities						
Facility ID: 203	370 Type:	WELL	API Number:	001-08879	Status:	SI	Insp	o. Status:	SI	
			Idla	M/~ II						
Purpose:	Chut In	Temporarily /	Idle \	Reminder:						
Comme				Merrinder						
Corrective Acti							Date	<b>.</b> .		
Corrective Acti	OII.		Dunde	unilog d			Date	Date:		
Data of Loot Dub d	Tank 00/07/0000			enHead						
	Test: 09/27/2022	_	Annual Brhd Co							
Last Brhd Test Re		f Csg Pressure: Csg Pressure:	:0	Fluid Type:						
Common	:: Appears to be pl						]			
							] ]			
Corrective Action	l:						Date:			
			COGCC	Comments Comments						
Comment						User		Date		
COGCC Inspect	ion Report Sumr	mary				finken	finkenbc 11/04/2		22	
Operator: Extract Location name: API # 001-08879 Location ID #: 37 County: Adams While there, I ob During this insperse of the designated standard	Kraft 34-14 2) 20290 served a shut in ection the followings, dead weeds, setback, remove as See attached phis site inspection res have been corry of inspection respection respective respe	well. ng possible co, trash, debris and ohoto # 3. n needs to be rrected to con	ompliance issues & unnecessary / I weeds per Rule conducted to en mply with COGCO	unused equipr 606. Corrective sure the	nent. Within	)				
		L. 11	-1-1 / I-P	. I. A I I	1 1					
		•		<u>пк/)</u> and search	by accumer	nt numbe	er: 			
	INSPECTION					x?Docume	ocumentId=5905772			
					tPDF.asp	x?Docume	entId=59057	7 <u>68</u>		
Attached Document You can go to C Document Num 403219486 700901256	OGCC Images (I Description INSPECTION SUBMITTED	L L		state.co.us/Down	loadDocumen	tPDF.asp	x?Docume			