

# Inspection Photos

API: 071-07604

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 12/12/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 12/12/2022

## Inspection Photos



**Photo 1.** Facing east toward the access road stream crossing. There is erosion beginning to occur in this area and needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 12/12/2022

## Inspection Photos



**Photo 2.** Facing southeast along the access road. This culvert along the access road has filled back in with sediment and needs to be cleaned out.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 12/12/2022

## Inspection Photos



**Photo 4.** Facing south along the access road. Other culverts along the road have been cleaned out and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 12/12/2022

## Inspection Photos



**Photo 4.** There was repairs made since previous inspection however erosion is occurring around the rock check dams. BMP maintenance is needed and additional BMP's should be installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07604 | Date: 12/12/2022

## Inspection Photos



**Photo 5.** Facing south toward the well site.

