

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2022

Submitted Date:

12/29/2022

Document Number:

702801090**FIELD INSPECTION FORM**
 Loc ID 334613 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                     | Comment                         |
|--------------|-------|---|---------------------------------|
| ,            |       | COGCC.inspections@caerus<br>oilandgas.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num | Facility Name             | Insp Status |
|-------------|----------|--------|-------------|------------|---------|---------------------------|-------------|
| 334613      | LOCATION | AC     |             |            | -       | SHIDELER-67S93W<br>25NWSW | RI          |

**General Comment:**

On 12/27/2022, Reclamation Specialist O'Malley conducted an interim reclamation and stormwater inspection at Caerus Piceance LLC's SHIDELER-67S93W/25NWSW Location #334613 in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Tank battery sign absent
- Open ended piping at tank battery and separators
- Bull plugs not installed on tank drains

Refer to the "Location," "Reclamation," and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | BATTERY                                 |       |            |
| Comment:             | Sign not posted at battery.             |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.e. | Date: | 02/27/2023 |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

|                           |  |       |            |
|---------------------------|--|-------|------------|
| <b>Good Housekeeping:</b> |  |       |            |
| Type                      | OTHER  |       |            |
| Comment:                  | Bull plugs not installed on tank drains.   |       |            |
| Corrective Action:        | Install bull plugs.  | Date: | 01/08/2023 |
| Type                      | OTHER  |       |            |
| Comment:                  | Open ended piping at tank battery. No control measures to prevent wildlife entry observed. |       |            |
| Corrective Action:        | Eliminate possibility of wildlife to enter open lines.                                     | Date: | 01/08/2023 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |



**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment No anchors observed.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

|  |   |
|--|---|
| 1003b. Area no longer in use? <u>Pass</u>  | Production areas stabilized ? <u>Pass</u>   |
| 1003c. Compacted areas have been cross ripped? _____   |   |
| 1003d. Drilling pit closed? _____  | Subsidence over on drill pit? _____   |
| Cuttings management: _____   |   |
| 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u> |   |
| Production areas have been stabilized? <u>Pass</u>   | Segregated soils have been replaced? _____  |
| <b>RESTORATION AND REVEGETATION</b>  |   |
| <u>Cropland</u>  |   |
| Top soil replaced _____  | Recontoured _____ Perennial forage re-established _____   |
| <u>Non-Cropland</u>  |   |
| Top soil replaced _____  | Recontoured <u>Pass</u> 80% Revegetation <u>In</u>  |
| 1003e. INTERIM VEGETATION TRANSECT   |   |
| TRANSECT RESULTS OF DISTURBED AREA% _____  |   |
| TRANSECT RESULTS OF REFERENCE AREA% _____  |   |
| TOTAL % OF DESIRABLE VEGETATION COVER _____  |   |
| VEGETATIVE COVER _____   |   |
| 1003 f. Weeds Noxious weeds? <u>P</u>  |   |
| Comment  | Areas of the location not needed for production, or no longer in use have been reduced and reclaimed. Interim areas appear vegetated with introduced perennial grasses. Snow cover and dormant season prevented full vegetation assessment. Previous reclamation inspection document #696203209 observed interim areas of the Location have achieved a uniform perennial vegetative establishment. No follow up required. |
| Corrective Action  |   |
| Date _____   |   |
| Overall Interim Reclamation <u>In Process</u>  |   |
| <b><u>Final Reclamation/ Abandoned Location:</u></b>   |   |
| Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____  |   |
| Final Land Use: _____  |   |
| Reminder: _____  |   |
| Comment: <div style="border: 1px solid black; height: 20px;"></div>  |   |
| Well plugged _____   | Pit mouse/rat holes, cellars backfilled _____   |
| Debris removed _____   | No disturbance /Location never built _____  |
| Access Roads _____   | Regraded _____ Contoured _____ Culverts removed _____   |
| Gravel removed _____   |   |
| Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____                    |   |
| Compaction alleviation _____ Dust and erosion control _____  |   |
| Non cropland: Revegetated 80% _____ Cropland: perennial forage _____   |   |
| Weeds present _____ Subsidence _____   |   |
| 1004.d. FINAL VEGETATION TRANSECT  |   |
| TRANSECT RESULTS OF DISTURBED AREA% _____  |   |
| TRANSECT RESULTS OF REFERENCE AREA% _____  |   |
| TOTAL % OF DESIRABLE VEGETATION COVER _____  |   |
| VEGETATIVE COVER _____   |   |
| Comment: <div style="border: 1px solid black; height: 20px;"></div>  |   |

|   |   |
|---|---|
| Corrective Action: <input style="width: 90%;" type="text"/> | Date: <input style="width: 90%;" type="text"/>  |
| Overall Final Reclamation <input type="checkbox"/>          | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

  

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       |                 |                         |                       |               |                          |         |
| Seeding          |                 |                         |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |

Comment: 

No stormwater issues observed in visible portions of the location. Location and access road are frozen and snow covered at the time of this inspection; unable to perform full stormwater inspection.

Corrective Action:

Date:

**Pits:**    ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 702801091    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5964554">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5964554</a> |