

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2022

Submitted Date:

12/30/2022

Document Number:

690203741**FIELD INSPECTION FORM**Loc ID 309410 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------|---------|
| WARD, GIENA | | gward@ogrisop.com | |
| BACA DAVID | | dbaca@ogrisop.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 294634 | WELL | PR | 07/18/2008 | CBM | 071-09496 | NEW ELK 25-08 | RI |

General Comment:

This is a location inspection.
See attached photos and additional details within this report.

Location

| | | | |
|--------------------|------|-------|--|
| Lease Road: | | | |
| Type | Main | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------|--|--|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | Date: | | |

Overall Good: ☐

| | | | | |
|--------------------|---|----------|--|------------------|
| Spills: | | | | |
| Type | Area | Volume | | |
| | | <= 1 bbl | | |
| Comment: | There is oil stained soils at the wellhead. There is water at the meter shed which may be a dripping leak. | | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | | | Date: 01/03/2023 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|--|------------------|
| Fencing/: | | | |
| Type | PIT | | |
| Comment: | The electric fence is in disrepair around the pit. A more robust fencing should be installed. | | |
| Corrective Action: | Comply with the fencing requirements per the 1002a rules | | Date: 01/13/2023 |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 403276221 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5965262 |
| 690203742 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5965258 |

