

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2023

Submitted Date:

02/12/2023

Document Number:

707600943

FIELD INSPECTION FORM

Loc ID 310092 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296035	WELL	TA	09/01/2019	OW	123-25884	WELLS RANCH USX AA35-16	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.439947 / -104.399059

Abandoned Centralized Battery formerly served 5 Location IDs (306642, 302641, 302639, 310092, 310131).
(Well(s): 4: Temporarily Abandoned | TA, 1: Plugged & Abandoned | PA).

Location				
Lease Road:				
	Type Access			
	comment: Adequate			
Corrective ActionL				Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type WELLHEAD			
	Comment:			
Corrective Action:				Date:
Emergency Contact Number:				
	Comment: <input style="width: 100%;" type="text"/>			
Corrective Action:	<input style="width: 100%;" type="text"/>			Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type WELLHEAD			
	Comment: Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 1			corrective date
	Comment: Appears plumbed to surface.			
Corrective Action:				Date:
Type: Other	# 1			
	Comment: Wellhead: w/ Master, casing valves.			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:	<input style="width: 100%;" type="text"/>			
Corrective Action:				Date:
Flaring:				
Type	<input style="width: 100%;" type="text"/>			
Comment:	<input style="width: 100%;" type="text"/>			
Corrective Action:				Date:

Inspected Facilities

Facility ID: 296035 Type: WELL API Number: 123-25884 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Well disconnected from flowline.
Battery Abandoned.
COGCC records last production: 01/2017.
SI/TA well per variance doc. #401474555. (NOBLE).
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.

Form 4 on file. TA date: 06/04/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 07/01/2015. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 04/27/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 02/10/2023 at approximately 16:40 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH USX-66N63W/35SESE Location ID: 310092 Well Name(s): Well Ranch USX AA35-16. API: 123-25884. Location County: Weld County, Colorado Weather: Sunny, damp w/ partial snow coverage.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.439947 / -104.399059</p> <p>Abandoned Centralized Battery formerly served 5 Location IDs (306642, 302641, 302639, 310092, 310131). (Well(s): 4: Temporarily Abandoned TA, 1: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/12/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707600944	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6017996