

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/23/2023

Submitted Date:

02/27/2023

Document Number:

707800202**FIELD INSPECTION FORM**
 Loc ID 334624 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:22 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285834	WELL	PR	09/18/2007	GW	045-12562	MILLER 14B-36-692	PR
285835	WELL	PR	03/03/2016	GW	045-12561	MILLER 14D-36-692	PR
285836	WELL	PR	12/03/2008	GW	045-12560	MILLER 13B-36-692	PR
285837	WELL	PR	08/31/2007	GW	045-12559	MILLER 24D-36-692	PR
285838	WELL	PR	12/03/2008	GW	045-12558	MILLER 24B-36-692	PR
285839	WELL	PR	08/31/2007	GW	045-12557	MILLER 23B-36-692	PR
288532	WELL	PR	08/31/2007	GW	045-13289	MILLER 13A-36-692	PR
288533	WELL	PR	12/03/2008	GW	045-13288	MILLER 14C-36-692	PR
288534	WELL	PR	08/31/2007	GW	045-13287	MILLER 23A-36-692	PR
288550	WELL	PR	09/18/2007	GW	045-13295	MILLER 14A-36-692	PR
288552	WELL	PR	08/31/2007	GW	045-13293	MILLER 24C-36-692	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 2/23/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Miller 23B, at Location # 334624 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Inspection is conducted also for complaint on CB4 SWD. I witnessed in the time frame of inspections around CB4 SWD 3 bob tail trucks and 1 transport truck in the 4 hours of inspections at locations in close proximity to CB4 SWD.

C/A (storm water) from previous inspection document # 700702285 could not be assessed due to heavy snow cover.

During this inspection the following compliance issues were observed:

1. Stored/unused equipment (ECD disconnected)
2. Two tanks missing labeling
3. Two tanks have faded labels
4. Some well head signs are faded and illegible
5. Random debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Some well head signs are faded and illegible		
Corrective Action:	Provide legible and proper signage	Date:	03/27/2023
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	1. Two tanks missing labeling 2. Two tanks have faded labels		
Corrective Action:	Provide proper labeling on tanks	Date:	03/27/2023
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: TEP 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	03/10/2023
Type	STORAGE OF SUPL		
Comment:	Stored/unused equipment (ECD disconnected)		
Corrective Action:	Remove unused/stored equipment	Date:	03/27/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 11		corrective date
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	See unused/stored equipment for C/A		
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 14		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	8	OTHER	HEATED STEEL AST		,	
Comment:	4 tanks are not heated					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	625 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	285834	Type:	WELL	API Number:	045-12562	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285835	Type:	WELL	API Number:	045-12561	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285836	Type:	WELL	API Number:	045-12560	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285837	Type:	WELL	API Number:	045-12559	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285838	Type:	WELL	API Number:	045-12558	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	285839	Type:	WELL	API Number:	045-12557	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	288532	Type:	WELL	API Number:	045-13289	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	288533	Type:	WELL	API Number:	045-13288	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	288534	Type:	WELL	API Number:	045-13287	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	288550	Type:	WELL	API Number:	045-13295	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	288552	Type:	WELL	API Number:	045-13293	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Ditches				
Berms						
		Culverts				

Comment: [C/A \(storm water\) from previous inspection document # 700702285 could not be assessed due to heavy snow cover.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403333399	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6035997
707800206	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6035981