

Inspection Photos

API: 071-08769

Operator: WAPITI OPERATING LLC

Inspection Date: 3/22/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08769 | Date: 3/22/2023

Inspection Photos



Photo 1. This culvert inlet was cleaned out by the Operator however, the culvert is full of sediment and the inlet has filled back in with sediment. Previous corrective action was not completed. Lat/Long:37.00581,-104.83861.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/22/2023

Inspection Photos



Photo 2. There is an erosion gully along the road that needs to be repaired and stabilized. It appears grading operations has partially filled in this gully however it still needs to be stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/22/2023

Inspection Photos



Photo 3. The side of the road is eroded and not stabilized. Erosion head cutting is continuing to occur further back into the slope. This area needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel. Lat/Long:36.99952,-104.83425.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/22/2023

Inspection Photos



Photo 4. The side of the road is eroded and not stabilized. Erosion head cutting is continuing to occur further back into the slope. This area needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel. Lat/Long:36.99952,-104.83425.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/22/2023

Inspection Photos



Photo 5. Further along the road near the Colorado line. The roadside and road is eroded and needs to be repaired and stabilized. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/22/2023

Inspection Photos



Photo 6. This culvert inlet was cleaned out however, the culvert is full of sediment which needs to be cleaned out. Lat/Long:36.99405,-104.84710.

Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/22/2023

Inspection Photos



Photo 7. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 3/22/2023