

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2023

Submitted Date:

06/13/2023

Document Number:

708300565

FIELD INSPECTION FORMLoc ID 323851 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10770

Name of Operator: VISION ENERGY LLC

Address: P O BOX 370

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

8 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|----------------------|---------|
| ENERGY, VISION | | mco@visionenergy.biz | |
| Byers, Jim | | jbyers@blm.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 210985 | WELL | PR | 03/01/2021 | CBM | 045-06743 | SOUTH SHALE RIDGE 10-7 | PR |

General Comment:**COGCC Inspection Report Summary**

On 6/12/2023 at approximately 16:20, Compliance Inspector Matthew Morris conducted an on-site inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE at Location ID #323851 in Garfield County, Colorado.

Corrective actions from FIR #708300367 have not been completed and remain in effect.

During the inspection, the following compliance issues were observed:

- 1) Weeds have encroached on all production equipment
- 2) Unused equipment stored on location
- 3) Leak at wellhead stuffing box
- 4) Stained soil at wellhead and in tank battery berm
- 5) Gas meter calibration record not conspicuously posted
- 6) Tank battery berm permeability inadequate due to weed growth
- 7) Inaccurate tank label on produced water tank
- 8) Open-ended line on produced water tank

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|---|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Inaccurate information (wrong operator) on tank label on produced water tank. | | |
| Corrective Action: | Install accurate labels on tank to comply with Rule 605. | Date: | 07/13/2023 |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911/(970) 858-8550

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | Stained soil present at wellhead and in tank battery. | | |
| Corrective Action: | Control and clean stained soil to comply with Rule 912. | Date: | 07/13/2023 |
| Type | WEEDS | | |
| Comment: | Weeds have encroached all production equipment on location. | | |
| Corrective Action: | Remove weeds to comply with Rule 606. | Date: | 03/21/2023 |
| Type | STORAGE OF SUPL | | |
| Comment: | Unused equipment stored on location. | | |
| Corrective Action: | Remove unused equipment to comply with Rule 606. | Date: | 06/02/2023 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|-----------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------------------|---|------------------|
| Type: Pump Jack | # 1 | |
| Comment: | Leak on pump jack stuffing box. | |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and production Facilities to ensure good mechanical condition to comply with Rule 608. | Date: 06/28/2023 |
| Type: Gas Meter Run | # 1 | |
| Comment: | Gas meter calibration record not conspicuously posted. | |
| Corrective Action: | Display legible gas meter calibration record in a conspicuous location to comply with Rule 430.d.(2). | Date: 03/24/2023 |
| Type: Horizontal Heated Separator | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|--|----------|-----------|---------|------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 200 BBLS | STEEL AST | | , |
| Comment: | Open-ended line on produced water tank. | | | | |
| Corrective Action: | Secure tank lines to comply with Rule 608. | | | | Date: 06/28/2023 |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|--|---------------------|---------------------|------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Inadequate | Walls Insufficient | Base Insufficient | Inadequate |
| Comment: | Berm permeability insufficient due to weed growth. | | | |
| Corrective Action: | Repair berm to comply with Rule 603.o. | | | Date: 04/14/2023 |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | |
|----------------------|------------|-----------------------|------------|
| Facility ID: 210985 | Type: WELL | API Number: 045-06743 | Status: PR |
| Insp. Status: PR | | | |
| Producing Well | | | |
| Comment: | Producing | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | | | | | |
| | | Sediment Traps | | | | |
| Berms | | | | | | |
| | | Culverts | | | | |
| | | Berms | | | | |
| Compaction | | | | | | |
| | | Ditches | | | | |
| | | Rip Rap | | | | |
| | | Gravel | | | | |
| | | Compaction | | | | |

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403432725 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145891 |
| 708300566 | Photo Log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145886 |