

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2023

Submitted Date:

06/13/2023

Document Number:

708300567

FIELD INSPECTION FORMLoc ID 324270 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10770

Name of Operator: VISION ENERGY LLC

Address: P O BOX 370

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	
Byers, Jim		jbyers@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266869	WELL	SI	09/01/2009	CBM	045-09853	SOUTH SHALE RIDGE 1-14H	SI

General Comment:**COGCC Inspection Report Summary**

On 6/12/2023 at approximately 16:40, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE at Location ID #324270 in Garfield County, Colorado.

Corrective actions from FIR #708300369 have not been completed.

During the inspection, the following compliance issues were observed:

- 1) No signage present at wellhead
- 2) Weeds have encroached on entire production area
- 3) Gas meter calibration record not conspicuously posted
- 4) Tank berm permeability insufficient due to weed growth
- 5) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No sign at wellhead.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/13/2023
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 858-8550

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds have encroached on entire production area.		
Corrective Action:	Remove weeds and invasive plants to comply with Rule 606.	Date:	05/10/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration record not conspicuously posted.		
Corrective Action:	Display legible gas meter calibration record in a conspicuous location to comply with Rule 430.d.(2)	Date:	05/13/2023
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on Bradenheads. All Bradenhead valves are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1		FIBERGLASS AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	Tank berm permeability insufficient due to weed growth.				
Corrective Action:	Repair tank berm to comply with Rule 603.				Date: 06/03/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	266869	Type:	WELL	API Number:	045-09853	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Last produced August 2009. Last MIT performed November 2021.									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					Location lacks stabilization
Berms						
Other	Fail					Insufficient vehicle tracking BMPs
Waddles	Fail					BMP is degraded and insufficient
		Other	Fail			Insufficient vehicle tracking BMPs
		Compaction	Fail			Access road lacks stabilization

Comment: 1) Rill erosion causing sediment transport from location into nearby vegetation
 2) Rill erosion causing sediment transport from access road running through location into adjacent drainage ditch
 3) Insufficient vehicle tracking BMPs in place to minimize transportation of sediment from location and access road

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002

Date: 06/03/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403432726	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145892
708300568	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145887