

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2023

Submitted Date:

06/13/2023

Document Number:

708300569

FIELD INSPECTION FORM

 Loc ID 312598 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments8 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
ENERGY, VISION		mco@visionenergy.biz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221992	WELL	SI	04/01/2010	CBM	077-08594	SOUTH SHALE RIDGE 1-14	SI

General Comment:[COGCC Inspection Report Summary](#)

On 6/12/2023 at approximately 16:35, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE at Location ID #312598 in Mesa County, Colorado.

Corrective actions from FIR #708300312 have not been completed.

During the inspection, the following compliance issues were observed:

- 1) Weeds/undesirable plant species present throughout production area
- 2) Tank battery berm has inadequate permeability due to weed growth
- 3) Trash and debris on location which includes a fire pit and burned trash
- 4) Inaccurate operator information on battery sign and wellhead sign
- 5) Gas meter calibration record not conspicuously posted
- 6) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Battery sign has inaccurate operator information.		
Corrective Action:	Install battery sign with correct information to comply with Rule 605.h.	Date:	05/18/2023
Type	WELLHEAD		
Comment:	Wellhead sign has inaccurate operator information.		
Corrective Action:	Install wellhead sign with correct information to comply with Rule 605.d.	Date:	05/18/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	TRASH		
Comment:	Burned trash present on location.		
Corrective Action:	Remove trash from location to comply with Rule 606.	Date:	04/25/2023
Type	WEEDS		
Comment:	Weeds and undesirable plant species present throughout production area.		
Corrective Action:	Remove weeds and undesirable plant species to comply with Rule 606.	Date:	04/25/2023
Type	DEBRIS		
Comment:	Fire pit and other debris present on location.		
Corrective Action:	Remove debris from location to comply with Rule 606.	Date:	04/25/2023

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration record not conspicuously posted.		
Corrective Action:	Display legible gas meter calibration record in a conspicuous location to comply with Rule 430.d.(2).	Date:	06/23/2023
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:							
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	300 BBLs	STEEL AST				
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate			
Comment:		Containment is not sufficiently impervious to contain spilled or released materials due to weed growth.					
Corrective Action:		Repair berm and remove weeds to comply with Rule 603.o.				Date:	05/18/2023
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 221992 Type: WELL API Number: 077-08594 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Waddles	Fail					BMP degraded and insufficient
		Compaction	Fail			Access road lacks stabilization
Other	Fail					Insufficient vehicle tracking BMPs
		Other	Fail			Insufficient vehicle tracking BMPs
Rip Rap						

Comment: 1) Erosion cutting under waddles allowing transport of sediment from location
2) Inadequate tracking BMP on lease road to/from location entrance
3) Sediment transport from lease road has encroached onto nearby vegetation

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403432727	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145893
708300570	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145888