

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2023

Submitted Date:

06/13/2023

Document Number:

708900749

FIELD INSPECTION FORMLoc ID 336023 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284991	WELL	PR	02/10/2010	GW	045-12337	HANGS A2	PR
284993	WELL	PR	02/10/2010	GW	045-12339	HANGS A4	PR

General Comment:**COGCC Inspection Report Summary**

On 06/13/2023 at approximately 12:05 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC Hangs A Pad.

Location # 336023 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas & Bald Eagle Roost Site as well as within close proximity to NSO Habitat & Bald Eagle Nest Site.

Location is within 411a Surface Water External Buffer & 411b Generalized External Buffer.

Location is approximately 588 yards from the Colorado River

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Failure to maintain chemical BMP with a CA date of 06/16/2023
2. Housekeeping - Unused Equipment with a CA date of 07/13/2023
3. Tanks & Berms - Secondary containment needs maintenance with a CA date of 07/03/2023
4. Meter calibration info not conspicuously posted with a CA date of 06/23/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location - ECD is disconnected & not operational		
Corrective Action:	The storage of equipment not necessary for use on location is prohibited.	Date:	07/13/2023
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank - cattle panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	06/23/2023
Type: Emission Control Device	# 1		
Comment:	Unused equipment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	2 deadman marked & 1 deadman improperly marked		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Pressure transducers & Taylor plugs located on both bradenhead, bradenhead valves are accessible. Bradenhead line is connected to flowline on both wells.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	Both wells on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Containment liner needs maintenance				
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.				Date: 07/03/2023

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	284991	Type:	WELL	API Number:	045-12337	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	284993	Type:	WELL	API Number:	045-12339	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Ditches						
Berms						
				Material Handling And Spill Prevention	Fail	Failure to maintain chemical BMP
Compaction						Small areas of light compaction
		Gravel				
Gravel						Sparse

Comment: [Chemical containment approximately 5/8 full/Failure to maintain chemical BMP](#)

Corrective Action: [Operators shall implement BMPs in accordance with good engineering practices, including measures such as: Materials handling and spill prevention procedures and practices implemented for material handling and spill prevention of materials used, stored, or disposed of that could result in discharges causing pollution of surface waters.](#)

Date: 06/16/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping, Equipment, Tanks & Berms & Stormwater for observed compliance issues.	smelserw	06/13/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403432639	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145776
708900750	Inspection 708900749 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145772
708900751	Inspection 708900749 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6145773