

**Inspection Photos**  
**Location Name: State 2-12**  
**Location ID: 328919**



**Photo 1 – Wellhead**

**Photo 2 – Stained Soil at Hardline Connection**

**Inspection Photos**  
**Location Name: State 2-12**  
**Location ID: 328919**



**Photo 3 – Temp Tank – No labels**

**Photo 4 – Temp Tank – No labels**

**Inspection Photos**  
**Location Name: State 2-12**  
**Location ID: 328919**



**Photo 5 – Temp Tank – No labels**



**Photo 6 – Temp Tank – No labels**

Inspection Photos  
Location Name: State 2-12  
Location ID: 328919



Photo 7 – Wellhead Sign

Photo 8 – Stained Soil at Exhaust

**Inspection Photos**  
**Location Name: State 2-12**  
**Location ID: 328919**



**Photo 9 – Strom Water in Containment**

**Photo 10 – Gas Engine**