

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2023

Submitted Date:

06/20/2023

Document Number:

702501471

**FIELD INSPECTION FORM**Loc ID 445610 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron	(970) 765-6300	aaron.katz@state.co.us	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Burger, Craig	(970) 319-4194	craig.burger@state.co.us	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

**General Comment:****COGCC Inspection Report Summary**

On Tuesday, 06/20/2023, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the Ant Hill Unit Wyatt 31-12, Location #445610, in Rio Blanco County, Colorado.

This location is within or in close proximity to a CPW District with Black Bear, High Priority, NSO, Density and Other Consultation Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

During Inspection #702501458 on 6/14/23 gurgling could be heard coming from around wellhead. Operator in my presence verified Surface casing had no pressure and dug down far enough to confirm no loose fittings on wellhead. Talked to Aaron Katz, Denver engineer and decided to have Operator dig out to conductor pipe to possibly confirm Wasatch gas migration. Cellar ring was excavated by hand down 4 feet to top of conductor. Met Operator on location this morning to verify. Gurgling could be heard but nothing could be seen. Trickled fresh water around wellhead. Confirmed bubbling was coming up outside the surface casing inside the conductor and some bubbling occurring around the outside of the conductor pipe. Surface (Bradenhead) casing – 0 psi. Tbg – 573 psi. Csg – 586 psi. Well is shut in due to compressor station shut down. Refer to Inspection Photos for observed findings.

Engineering to advise if any further action is required.

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501472	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154932">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154932</a>

702501474	Video 64	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154933">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154933</a>
702501475	Video 66	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154934">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154934</a>
702501476	Video 67	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154935">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154935</a>