

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2023

Submitted Date:

06/16/2023

Document Number:

690204332

FIELD INSPECTION FORMLoc ID 333537 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
SIMCOE		sjninspections@ikavenergy.co	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215423	WELL	PR	11/11/2015	CBM	067-07028	PETER PHILLIPS A 1	RI

General Comment:

On 6/16/2023, Ryan Costa conducted a follow up location and stormwater management inspection.
An inspection report will be issued to both Operators of the location.
See attached photos and additional details within this report

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	There are noxious weeds along the access road that need to be controlled. Corrective action needs to be addressed immediately. CA date is observed date of issue.		
Corrective Action:	Comply with Rule 1003.f.	Date:	06/15/2023

Overall Good: ☐

Spills:					
Type	Area	Volume			
Condensate	Tank				
Comment:	There is oil stained soils at the buried tank that need to be cleaned up. Stained soils were observed inside and outside of containment. Corrective action needs to be addressed immediately. CA date is observed date of issue.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.				Date: 06/15/2023

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Secondary containment may not be adequate due to stained soils outside of containment.			
Corrective Action:				
				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			
			Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: There is vehicle rutting along the access road that needs to be repaired and stabilized. Previous corrective action has not been completed.</p> <p>Corrective Action: Install or repair required BMPs per Rule 1002.f.(2) Date: 05/05/2023</p> <p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403436863	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6151329
690204333	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6151315