

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2023

Submitted Date:

06/16/2023

Document Number:

709400293

FIELD INSPECTION FORM

Loc ID 333183 Inspector Name: WOLD, REED On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		inspections@civiresources.com	
		lkelly@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248781	WELL	SI	03/01/2023	GW	123-16583	ARISTOCRAT ANGUS 21-8	RI
274645	WELL	AL	02/01/2007	LO	123-22550	ARISTOCRAT ANGUS 1-	RI
274699	WELL	SI	03/01/2023	GW	123-22561	ARISTOCRAT ANGUS 3-2-8	RI
333183	LOCATION	AC			-	ARISTOCRAT ANGUS 2-4-8	RI
412927	WELL	PR	01/02/2023	GW	123-30575	ARISTOCRAT ANGUS 2-4-8	RI
473102	OFF-LOCATION FLOWLINE	AC	02/21/2023		-	ARISTOCRAT ANGUS 2-4-8	RI
473103	OFF-LOCATION FLOWLINE	AC	02/21/2023		-	ARISTOCRAT ANGUS 2-4-8	RI
473104	OFF-LOCATION FLOWLINE	AC	02/21/2023		-	ARISTOCRAT ANGUS 2-4-8	RI
473105	OFF-LOCATION FLOWLINE	AC	02/21/2023		-	ARISTOCRAT ANGUS 2-4-8	RI
473106	OFF-LOCATION FLOWLINE	AC	02/21/2023		-	ARISTOCRAT ANGUS 2-4-8	RI

General Comment:

On 6/6/2023, Reclamation Specialist Reed Wold and Chris Binschus met with the complantant to conduct an Interim Reclamation and Stormwater inspection in response to a complaint. The following compliance issues were observed during this inspection:

- 1) 603.h. Fencing Requirements (completed prior to inspection)
- 2) 1002.f. Stormwater management
- 3) 606.c. Weeds
- 4) 606.d. Trash (concrete)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Old concrete on location in reclaimed pipeline right of way.		
Corrective Action:	Comply with Rule 606.d. Trash	Date:	06/06/2023
Type	WEEDS		
Comment:	Weeds starting to emerge on pipeline right of way, in disturbed areas.		
Corrective Action:	Comply with Rule 606.c. Weeds	Date:	06/06/2023

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Fencing was lacking around pot holed areas of pipeline excavation. Fencing has been installed since complaint or excavation filled in.		
Corrective Action:	None	Date:	06/06/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: <u>248781</u>	Type: <u>WELL</u>	API Number: <u>123-16583</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>274645</u>	Type: <u>WELL</u>	API Number: <u>123-22550</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>274699</u>	Type: <u>WELL</u>	API Number: <u>123-22561</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>333183</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>
Facility ID: <u>412927</u>	Type: <u>WELL</u>	API Number: <u>123-30575</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>473102</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>
Facility ID: <u>473103</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>
Facility ID: <u>473104</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>
Facility ID: <u>473105</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>
Facility ID: <u>473106</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						

Comment: Soil erosion accuring in disturbed areas of pipeline right of way, from removal of flowlines. Recent rains have caused run on into reseeded areas below culvert.

Corrective Action: Comply with Rule 1002.f.

Date: 06/06/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403436205	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6150670
709400294	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6150662