

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2023

Submitted Date:

06/20/2023

Document Number:

696305033

## FIELD INSPECTION FORM

Loc ID 328919 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
 Name of Operator: KP KAUFFMAN COMPANY INC  
 Address: 1700 LINCOLN ST STE 4550  
 City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 8 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email         | Comment |
|--------------|-------|---------------|---------|
|              |       | cogcc@kpk.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 248821      | WELL | PR     | 01/01/2023  | OW         | 123-16623 | STATE 2-12    | PR          |

**General Comment:**

[Follow-Up Inspection to 696304870 dated 05.10.2023](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |                                                                        |       |            |
|--------------------|------------------------------------------------------------------------|-------|------------|
| Type               | WELLHEAD                                                               |       |            |
| Comment:           | Adequate                                                               |       |            |
| Corrective Action: |                                                                        | Date: |            |
| Type               | TANK LABELS/PLACARDS                                                   |       |            |
| Comment:           | Temp Tank missing all Labels - Content, Capacity, and NFPA; see photos |       |            |
| Corrective Action: | Install sign to comply with Rule 605.h.                                | Date: | 07/21/2023 |

**Emergency Contact Number:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Comment:           | <input type="text"/> | Date: |  |
| Corrective Action: | <input type="text"/> | Date: |  |

**Good Housekeeping:**

|                    |                                                                                                        |       |            |
|--------------------|--------------------------------------------------------------------------------------------------------|-------|------------|
| Type               | OTHER                                                                                                  |       |            |
| Comment:           | Stained Soil at Hardline to Temp Tank and Engine Exhaust; see photos                                   |       |            |
| Corrective Action: | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." | Date: | 05/24/2023 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |
|------|------|--------|--|
|      |      |        |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type               | #                                | corrective date |
|--------------------|----------------------------------|-----------------|
| Deadman # & Marked | # 4                              |                 |
| Comment:           |                                  |                 |
| Corrective Action: |                                  | Date:           |
| Pump Jack          | # 1                              |                 |
| Comment:           |                                  |                 |
| Corrective Action: |                                  | Date:           |
| Bradenhead         | # 1                              |                 |
| Comment:           | Appears to be plumbed to surface |                 |
| Corrective Action: |                                  | Date:           |

**Tanks and Berms:**

| Contents           | #                                                              | Capacity | Type      | Tank ID | SE GPS |
|--------------------|----------------------------------------------------------------|----------|-----------|---------|--------|
| OTHER              | 1                                                              | 500 BBLs | STEEL AST |         |        |
| Comment:           | Temp Tank - No Berm, No Labels, Hardline hooked up to Wellhead |          |           |         |        |
| Corrective Action: |                                                                |          |           |         | Date:  |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 248821 Type: WELL API Number: 123-16623 Status: PR Insp. Status: PR

**Producing Well**

Comment: SI - Well Shut-In at the time of this Inspection. Wellhead is connected to Hardline to Temp Tank. No Tank Battery to Produced into

Corrective Action:

Date:

**COGCC Comments**

| Comment                                                                                                                                                                                                                             | User   | Date       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <u>Routine Field Inspection. SI - Well Shut-In at the time of this Inspection. Wellhead is connected to Hardline to Temp Tank. No Tank Battery to Produced into. Stained Soil at Hardline and Exhaust. Temp Tank missing Labels</u> | petrie | 06/20/2023 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL                                                                                                                                                                 |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 403440008    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154544">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154544</a> |
| 696305034    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154541">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6154541</a> |