

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/21/2023

Submitted Date:

06/23/2023

Document Number:

696205049

FIELD INSPECTION FORMLoc ID 322420 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 760 HORIZON DRIVE STE 400

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections	(970) 675-7928	inspections@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210458	WELL	SI	12/01/2022	GW	045-06214	W R YOUNG CATTLE CO B-12-6-104-S	RI
322420	LOCATION	AC			-	W R YOUNG CATTLE CO-66S104W 12NWNE	RI

General Comment:

On 6/21/2023, Reclamation Specialist Trujillo inspected Utah Gas Corp's WR Young Cattle Co B-12-6-104-S location in Garfield County, Colorado.

This inspection is a follow-up to #696204447 dated 12/5/2022, to document compliance with the following corrective actions:

- Anchors missing required marking
- Signage at tank battery
- Well Signage

This inspection is also in response to Resolution #403281389 stating corrective actions have been completed.

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

The following new compliance issues were observed per this inspection:

- Labeling at container
- Stormwater
- Undesirable Plant Species

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type			
comment:	See "Stormwater".		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Tank battery		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Previous inspection observed that signage was missing from the wellhead. Inspection required Operator to comply with Rule 605.d. It was observed in this inspection that signage remains missing at the wellhead. This CA has not been addressed and remains applicable.		
Corrective Action:	Comply with 605.d and install signage at the wellhead.	Date:	01/06/2023
Type	TANK LABELS/PLACARDS		
Comment:	Tank labeling		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Labeling at container located next to meter shed is missing, or no longer legible.		
Corrective Action:	Comply with 605.h. Corrective action date is "Date of Discovery"; Location will remain out of compliance until CA has been resolved.	Date:	06/21/2023
Emergency Contact Number:			
Comment:	970-693-6021 / 911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	Undesirable Plant Species, such as Hoary Cress, Kochia, knotweed, etc... were observed established on the Location, including road, production and interim areas.		
Corrective Action:	Comply with Ruled 606.c and 1003.f. Corrective action date is "Date of Discovery"; Location will remain out of compliance until CA has been resolved.	Date:	06/21/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog Paneling		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Livestock panels		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)	Produced water / Condensate Mix				
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares containment with 300 bbl Produced water / Condensate Mix tank				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)	Produced water / condensate mix				
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares containment with 400 bbl Produced water / Condensate Mix tank				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	210458	Type:	WELL	API Number:	045-06214	Status:	SI	Insp. Status:	RI
Facility ID:	322420	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? PassComment No waste or debris observed stored on the interim and production areas of the Location.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? PassComment No unused or unneeded equipment observed stored on the interim and production areas of the Location.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? PassComment Previous inspection observed anchors missing required marking. Inspection required Operator to install required marking.It was observed in this inspection that the anchors have been marked per 1003 rules.

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment [See "Good Housekeeping" for weed management requirements.](#)

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: It was observed in this inspection that stormwater and erosion control BMPs to stabilize and manage runoff are missing or insufficient at the access road; stormwater diversion ditch along road has not been installed, or maintained per good engineering practices, resulting in incising and gully erosion, and degradation to the road.</p> <p>Corrective Action: Install and maintain required stormwater and erosion control BMPs at the access road. Corrective action date is "Date of Discovery"; Location will remain out of compliance until CA has been resolved.</p>						<p>Date: 06/21/2023</p>
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403444021	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159047
696205050	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159044