

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2023

Submitted Date:

06/23/2023

Document Number:

697602127

FIELD INSPECTION FORM

Loc ID 323108 Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Graber, Nikki		nikki.graber@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244772	WELL	PR	06/01/2019	GW	123-12567	Jordan 34-3	EI

General Comment:

This is an environmental inspection in response to Spill ID 484635. Remedial excavation is open. Staining and hydrocarbon odor observed in the excavation where the produced water vessel was located. Excavation crews were onsite and were removing impacted soil from the excavation. Any corrective actions from previous inspections or forms that have not been addressed are still applicable. Photos are attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment: Signage is adequate.

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:				
Type	OTHER			
Comment:	Orange construction fencing around the excavation is adequate.			
Corrective Action:				Date:

Equipment:				
Type:		#		corrective date
Comment:	Equipment has been removed.			
Corrective Action:				Date:

Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 244772 Type: WELL API Number: 123-12567 Status: PR Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
Oily Soil			
Comment	Contaminated soil is stockpiled on a liner and is bermed. There are several other stockpiles on location with no indication if the stockpiles are clean or contaminated.		
Corrective Action	Comply with 1002. b rules for soil removal and segregation.		Date: 06/26/2023

Spill/Remediation:

Comment:	Excavation crews were onsite and were removing the impacted soil from the produced water vessel excavation. Gray staining was observed within the excavation. Water was also observed within the excavation.		
Corrective Action:			Date: _____

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot: _____	Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
The on-location flowline was removed and the excavation was still open at the time of the inspection.	ahmadiia	06/23/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403444187	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159245
697602128	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6159233