

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2023

Submitted Date:

06/26/2023

Document Number:

696305048

FIELD INSPECTION FORMLoc ID 331298 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 65110

Name of Operator: O'BRIEN ENERGY RESOURCES CORP

Address: 18 CONGRESS ST STE 207

City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Forma, Joe		joeforma@obenergy.com	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260339	WELL	TA	07/30/2020	GW	123-20458	LOST CREEK O'BRIEN 4-20	TA

General Comment:

Follow-Up Inspection to FIR 696304872 dated 05.12.2023

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Wellhead. See photos		
Corrective Action:	Comply with Rule 606	Date:	06/12/2023
Type	OTHER		
Comment:	Stained Soil on varies parts of Location; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	06/12/2023
Type	STORAGE OF SUPL		
Comment:	Unused Equipment, supplies and parts on Entire Location. See Photos (Tanks, Separators, Useable Pipes, Valves, Stairs, Tanks Catwalks) Remains - Original Corrective Action Date remains the same		
Corrective Action:	Requires a Variance to Store Equipment on Location	Date:	06/12/2023
Type	TRASH		
Comment:	Trash and Debris NEED to REMOVED from Location; see Photos Remains - Original Corrective Action Date remains the same		
Corrective Action:	Comply with Rule 606	Date:	06/12/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Disconnected from Flowline		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:	Shares berm with the Crude Oil Tank					
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.209670,-104.345370	
Comment:						
Corrective Action:						

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 260339 Type: WELL API Number: 123-20458 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: TA - MIT:02.26.2020

Please refer to Form 4 - 402860646 dated 11.02.2021 Approved on 12.08.2022 to continue TA Status by May 2023

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 06/15/2023 at approximately 13:17, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at O'Brien Energy Resources Corp, Lost Creek 4-20, Location #331298 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Trash - Everything in the Center of Location is TRASH and have 30 days (06.12.2023) to remove it from Location.</p> <p>Unused Equipment (Separators, Heater Treaters, Useable Pipe and Useable Equipment) needs to moved to the outer edge in a neat and orderly fashion. Corrective Action Date 06.12.2022</p> <p>Unmarked Riser at Wellhead. See Photos. Comply with Rule 606. Corrective Action Date 06.12.2023</p> <p>Stained Soil in various spots on Location. See Photos. Corrective Action Date 06.12.2023</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the Inspection Report</p>	petrie	06/26/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403445974	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6161319
696305049	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6161293