

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2023

Submitted Date:

06/29/2023

Document Number:

696305057

FIELD INSPECTION FORM

Loc ID: 454760 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10661
Name of Operator: CIVITAS NORTH LLC
Address: 555 17TH STREET #3700
City: DENVER State: CO Zip: 80202

Findings:

- 18 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454758	WELL	PR	03/27/2023	OW	123-46717	Grotheer 5-61 11A-2-5	PR
477805	WELL	PR	03/27/2023	OW	123-51222	Grotheer 5-61 11A-14-23-1	PR
477806	WELL	PR	03/27/2023	OW	123-51223	Grotheer 5-61 11A-2-1	PR
477808	WELL	PR	03/27/2023	OW	123-51225	Grotheer 5-61 11A-14-23-5	PR
477809	WELL	PR	03/27/2023	OW	123-51226	Grotheer 5-61 11A-14-23-3	PR
477811	WELL	PR	03/27/2023	OW	123-51228	Grotheer 5-61 11A-2-3	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash Dumpster overflowing and NOT covered; see photos		
Corrective Action:	Comply with Rule 606	Date:	07/31/2023
Type	STORAGE OF SUPL		
Comment:	Unused Building in North East Corner of Locaiton; see photos		
Corrective Action:	Comply with Rule 606	Date:	07/31/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 12		corrective date
Comment:			
Corrective Action:		Date:	

Type: LACT	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical and Automation Equipment		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Instrumental Air Units		
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Other	# 6		
Comment:	Sand Traps		
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.410510,-104.179730
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	454758	Type:	WELL	API Number:	123-46717	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	477805	Type:	WELL	API Number:	123-51222	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	477806	Type:	WELL	API Number:	123-51223	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	477808	Type:	WELL	API Number:	123-51225	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	477809	Type:	WELL	API Number:	123-51226	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	477811	Type:	WELL	API Number:	123-51228	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles						
Retention Ponds						
Ditches						
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Unused Building in NE Corner and Trash Dumpster overflowing and NOT covered	petrie	06/29/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403449955	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6165457
696305058	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6165410