

**TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306**



Drainage crossing access road

Stormwater crosses road before reaching culvert

TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306




Erosion and sediment migration



Debris

TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306



Production facility from well pad

Sign at separators

TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306



No visible display of gas meter calibration



Gas meter calibration not displayed

TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306



Open surface casing valve



Surface casing valve left open

TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306



Erosion and sediment migration



Erosion off location to production pad

TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306



Erosion and sediment migration from location



Wattles ineffective in places

TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306



Wattle failure



Wattle erosion

**TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306**



Location from Southeast corner



Location from Southwest corner

**TEP Rocky Mountain LLC
GM 14-27
Loc ID: 335306**



Location from Northeast corner



Location from Northwest corner