

FORM  
INSPRev  
X/20

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2023

Submitted Date:

07/05/2023

Document Number:

694100110

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
427430 \_\_\_\_\_ Robinson, Taylor \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 200642  
Name of Operator: CIVITAS RESOURCES INC  
Address: 555 17TH STREET SUITE 3500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Antonioli, Philip	720-345-4603	pantonioli@civiresources.com	
,		COGCCInspections@extracti onog.com	All Inspections
,		Inspections@civiresources.co m	

**General Comment:**

This is an environmental inspection for Location/Facility ID: 427430 Lamb 42-15 Facility. Any corrective actions from previous inspections that have not been addressed are still applicable. There were contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment: No signs on site. Site has been decommissioned. All equipment has been removed. Site seems to be ready for reclamation.

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: Oily substance was on location. Could be a small diesel or gasoline spill.

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:	<span style="color: blue;">Open excavation on location. Approximately 10ft x 12ft x 5ft.</span>		
Corrective Action:	<span style="color: red;">Fill open excavation. Install safety fencing until excavation can be filled in. Comply with the fencing requirements per the 1002a rules."For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e."" For larger instances: ""Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS""</span>	Date:	<u>07/20/2023</u>

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Oily substance was on location. Could be a small diesel or gasoline spill.

Corrective Action: "For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e."" For larger instances: ""Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS""" Date: 07/12/2023

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403453873	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169943">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169943</a>
694100111	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169928">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6169928</a>