

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/03/2023

Submitted Date:

07/05/2023

Document Number:

708300653

FIELD INSPECTION FORM

 Loc ID 312470 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments6 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
ENERGY, VISION		mco@visionenergy.biz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221711	WELL	PR	09/01/1995	GW	077-08313	FEDERAL 30-3	PR

General Comment:[COGCC Inspection Report Summary](#)

On 7/3/2023 at approximately 12:45, Compliance Inspector Matthew Morris conducted an on-site inspection at VISION ENERGY LLC, FEDERAL-68S97W/30SWSW at Location ID #312470 in Mesa County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Weeds present across entire production area
- 2) Debris on location
- 3) Bradenhead inaccessible or not visible
- 4) Door missing from gas meter house
- 5) Gas meter calibration record not conspicuously posted
- 6) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

Location			
Lease Road:			
Type	Main		
comment:	Main lease road crosses unprotected creek bed with no stormwater BMPs in place.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/(970) 858-8550		Date:
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds present across entire production area.		
Corrective Action:	Remove weeds to comply with Rule 606.		Date: 07/12/2023
Type	DEBRIS		
Comment:	Debris present on southern perimeter of pad.		
Corrective Action:	Remove debris to comply with Rule 606.		Date: 07/12/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fencing		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: 07/15/2023
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Door is missing on gas meter house.		
Corrective Action:	Secure gas meter house to comply with Rule 608.e.		Date: <u>07/20/2023</u>
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration record not conspicuously posted.		
Corrective Action:	Display legible gas meter calibration record in a conspicuous location to comply with Rule 430.d.(2).		Date: <u>07/15/2023</u>
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 221711 Type: WELL API Number: 077-08313 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Insufficient vehicle tracking BMPs
		Compaction				
Compaction	Fail					Location lacks stabilization

Comment: [Location lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations to comply with Rule 1002.](#)

Date: 07/20/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403454262	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6170328
708300654	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6170323