

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/03/2023

Submitted Date:

07/05/2023

Document Number:

708300655

FIELD INSPECTION FORMLoc ID 312511 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10770

Name of Operator: VISION ENERGY LLC

Address: P O BOX 370

City: IGNACIO State: CO Zip: 81137

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	
Byers, Jim		jbyers@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221818	WELL	TA	01/01/2021	GW	077-08420	FEDERAL 35-2	TA

General Comment:**COGCC Inspection Report Summary**

On 7/3/2023 at approximately 13:20, Compliance Inspector Matthew Morris conducted an on-site inspection at VISION ENERGY LLC, FEDERAL-68S98W/35SENW at Location ID #312511 in Mesa County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Weeds present near wellhead and in pits
- 2) Debris on location
- 3) Unused gas meter run on location
- 4) Wellhead sign not posted
- 5) Bradenhead inaccessible or not visible
- 6) No permit on file for two pits on location
- 7) No MIT on record for TA well

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

Location

Lease Road:			
Type	Access		
comment:	Access road to location crosses an unprotected creek bed with no stormwater BMPs in place.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead sign not posted.		
Corrective Action:	Post wellhead sign to comply with Rule 605.d.	Date:	08/04/2023

Emergency Contact Number:

Comment: 911/(970) 858-8550

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run on location.		
Corrective Action:	Remove unused equipment from locatino to comply with Rule 606.	Date:	08/04/2023
Type	WEEDS		
Comment:	Weeds present near wellhead and pits		
Corrective Action:	Remove weeds to comply with Rule 606.	Date:	07/12/2023
Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris to comply with Rule 606.	Date:	07/12/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	07/15/2023

Venting:

Yes/No	NO		
--------	----	--	--

Inspector Name: Morris, Matthew

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	221818	Type:	WELL	API Number:	077-08420	Status:	TA	Insp. Status:	TA	
Idle Well										
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		<div>Well last produced prior to 1999. No MIT on record.</div>								
Corrective Action:		<div>Perform successful mechanical integrity test. If a successful MIT can not be performed within the 30 day CA time, the well must be plugged within 3 months per Rule 417 and 210.</div>						Date:		08/04/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Compaction				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Lined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: InadequateComment: Two pits on location with no permit on record for either of them.

Corrective Action

Submit an eForm 15 Pit Report to update records with current information to comply with rule 908.Date: 07/20/2023**Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403454263	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6170330
708300656	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6170324