

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2023

Submitted Date:

07/12/2023

Document Number:

699106912**FIELD INSPECTION FORM**Loc ID 330074 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250552	WELL	PR	03/01/2019	GW	123-18355	HSR-HOBE STATE 2-32	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		Date:
Corrective Action:			

Good Housekeeping:		
Type	OTHER	
Comment:	Stained soil next to the well needs to be removed. See attached photo	
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date: 07/21/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Panel	
Corrective Action:		Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Master valve appears to be leaking "mechanical conditions". See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 07/21/2023
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:	
-----------------	--

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 250552 Type: WELL API Number: 123-18355 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/23/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary
 On Wednesday 7/12/23 at approximately 0754hrs I, Inspector Adam Burns,
 Conducted an on-site inspection at HSR-Hobe State 2-32 of KP KAUFFMAN COMPANY
 INC.

API #05-123-18355 in Weld County, Colorado.

During this inspection the following possible compliance issues were observed:
 Stained soil next to the well needs to be removed. "Properly dispose of oily waste in
 accordance with 905.e." With a Corrective Action date of 7/21/23

Master valve appears to be leaking "mechanical conditions". Securely fasten all valves,
 pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at
 regular intervals and maintain in good mechanical condition per Rule 608.e. With a
 Corrective Action date of 7/21/23

A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with ECMC rules.

This is a summary of the inspection report.

burnsa

07/12/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106913	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6178420