

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/26/2023

Submitted Date:

07/26/2023

Document Number:

708901137**FIELD INSPECTION FORM**
 Loc ID 335085 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266651	WELL	PR	06/30/2003	GW	045-09162	SCHIDELER 29-15 (O29NE)	PR
266652	WELL	PR	06/26/2003	GW	045-09160	SCHIDELER 29-14 (O29NE)	PR
282861	WELL	PR	01/26/2006	GW	045-11853	SHIDELER 29-11C (O29NE)	PR
282862	WELL	PR	05/22/2007	GW	045-11854	SHIDELER 29-15A (O29NE)	PR
282863	WELL	PR	06/03/2007	GW	045-11855	SHIDELER 29-14C (O29NE)	PR
282864	WELL	PR	06/03/2007	GW	045-11856	SHIDELER 29-15C (O29NE)	PR

General Comment:**CECMC Inspection Report Summary**

On 07/26/2023 at approximately 09:00 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at CAERUS PICEANCE LLC O29NE pad.

Location # 335085 in Garfield County Colorado.

Please refer to Inspection 708900476 conducted on 05/12/2023, previous corrective actions have been completed.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

Location is approximately 56 yards from Mamm Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Stained soils & gravel near production unit with a CA date of 08/05/2023

2. Equipment - Flowline heating insulation open ended with a CA date of 08/02/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the units indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Type	OTHER		
Comment:	Stained soils & gravel near production unit		
Corrective Action:	Remove and properly dispose of all stained soils & gravel.		Date: 08/05/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence		

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment: All wells on plunger lift			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment: Pressure transducers located on all bradenhead, all bradenhead valves are accessible.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Flowline heating insulation open ended			
Corrective Action: Operators will prevent & minimize adverse impacts to wildlife resources.		Date: 08/02/2023	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Summit Midstream meter & meter house			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,
Comment: Centralized containment					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	250 bbls
Other (Type)	

Berms

Inspector Name: Smelser, Wayne

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,

Comment:	Centralized containment	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	OTHER	HEATED STEEL AST		,

Comment:	Centralized containment	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	266651	Type:	WELL	API Number:	045-09162	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	266652	Type:	WELL	API Number:	045-09160	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282861	Type:	WELL	API Number:	045-11853	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282862	Type:	WELL	API Number:	045-11854	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282863	Type:	WELL	API Number:	045-11855	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	282864	Type:	WELL	API Number:	045-11856	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Gravel						
Berms						
		Paving				
Compaction						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping & Equipment for observed compliance issues.	smelserw	07/26/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901138	Inspection 708901137 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6196451
708901139	Inspection 708901137 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6196452