

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2023

Submitted Date:

07/26/2023

Document Number:

698600786**FIELD INSPECTION FORM**Loc ID 314031 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 2501 HARWOOD ST STE 1238City: DALLAS State: TX Zip: 75201**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**23 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Chambers, Kit		Kchambers@ravenwoodlabs.com	<u>7/16/2023</u>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
, Enforcement		dnr_cogccenforcement@state.co.us	
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	<u>7/16/2023</u>
Pesicka, Conor		conor.pesicka@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290236	WELL	PR	10/05/2007	GW	095-06120	GARRETT 15-33-6-45	PR

**General Comment:**Follow up Inspection to FIR Document #701603073 dated 04/12/2023.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Two track off maintained county road.			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Well sign is mounted to Meter Shed door.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<p>Document #701603073 comment: EMERGENCY CONTACT NUMBER ON SIGNAGE - (877) 425-4882 - F.I. CALLED (3) TIMES RECEIVING AN AUTOMATED MESSAGE THE NUMBER IS UNASSIGNED OR NO LONGER IN SERVICE.</p> <p>Follow up Inspection: Emergency contact #713-830-6800 posted on well sign message when call states disconnected or no longer in service.</p> <p>Corrective Action Date remains the same.</p>			
Corrective Action:	<p>COMPLY WITH RULE 600 SERIES.</p> <p>Follow up Inspection: Install sign to comply with Rule 605.d.</p>			Date: 05/10/2023
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Stained soils around wellhead and water collecting around wellhead base with oily sheen.			
Corrective Action:	Clean up and properly dispose of oily waste in accordance with 905.e.		Date:	07/31/2023
Type	DEBRIS			
Comment:	<p>Document #701603073 comment: REMOVE DEBRIS @ WELLHEAD</p> <p>Follow up Inspection: T Post, Wooden Post, and production related debris inside and outside well fencing.</p>			
Corrective Action:	Comply with Rule 606		Date:	08/04/2023
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
Other	Flow Line			
Comment:	UPON ARRIVAL NG RELEASING INTO ATMOSPHERE AND MR SHED. See attached photograph			
Corrective Action:	<p>Securley fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition Per Rule 608.e.</p> <p>Follow up Inspection: At time of inspection there was no noted/visible repairs or remediation activities noted. Corrective Action date remains the same.</p>			Date: 04/13/2023
Lube Oil	Pump Jack			

Comment:	REMOVE/REMEDiate/DISPOSE ACCULUMATED DEPOSIT OF LUBE OIL ON PJ PAD OR REMOVE PAD. PJ HAS BEEN REMOVED				
Corrective Action:	COMPLY WITH RULE 906			Date:	04/13/2023
	Follow up Inspection: At time of inspection there was no noted/visible repairs or remediation activities noted. Corrective Action date remains the same.				
Produced Water	Flow Line	<= 1 bbl			
Comment:	VALVE AT WELLHEAD OPEN UPON ARRIVAL. EXPOSED LEAK OF N/G + PW. SEVERE CORROSION ON PIPE AND VALVE. RELEASE CONTROLLED / WELL VALVE SI BY COGCC STAFF. SEE ATTACHED PHOTOGRAPH				
Corrective Action:	CONTROL AND CONTAIN SPILLS/RELEASES AND REMEDIATE PER RULE 900 series - 912.a., 912.b., 905.c., 905.c. . . , RULE 1000 series - PROPERLY TREAT OR DISPOSE IN ACCORDANCE WITH RULE 905.f. Notify EPS (spill report) within (24) hrs. of this FIR notification - (48) hrs. to perform cleanup per RULE 912.			Date:	04/13/2023
	Follow up Inspection: At time of inspection there was no noted/visible repairs or remediation activities noted. Corrective Action date remains the same.				

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Stock panel fencing around all surface equipment at well location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Steel Meter Shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	GAS METER CALIBRATION - METER NOT CALIBRATED ANNUALLY - LAST DATE OF CALIBRATION SIGNATURE ON CARD 07/14/2020. SEE ATTACHED PHOTOGRAPH		
	Follow up Inspection: Chart in meter box is dated 12-1-22. Meter calibration dated 7-14-20.		
Corrective Action:	CALIBRATE GAS METERING EQUIPMENT ANNUALLY TO COMPLY WITH RULE 430.d.(1)		Date: 05/11/2023
	Follow up Inspection: No corrective actions taken corrective action date remains the same.		
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing appear to be in wellbore. Tubing valve closed. Casing valve closed.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Concrete slab (Pump Jack).		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Located 4 anchors. Markers are two short, faded, and barely visible.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	07/26/2023
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290236	Type:	WELL	API Number:	095-06120	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Casing valve closed. Tubing valve closed. Well appears to be Shut In. Gas meter chart in meter box at time of inspection is dated 12-1-22. Review of electronic well file reflects last reported production status is 8/1/2022.								
Corrective Action:	Submit required Form 7(s) to COGCC per rule 413.							Date:	08/28/2023

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: Leak in flowline @ MR

Corrective Action:

Control and contain spills/releases and clean up Per Rule 912.a., Rule 912.b., Rule 912.c Follow up Inspection: At time of inspection there was no noted/visible repairs or remediation activities noted. Review of electronic well file does not reflect Form 19 filing by Operator. Corrective Action date remains the same.

Date: 04/13/2023

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water:

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Original comments and corrective action for FIR document #701603073 are in all capital spelling. Follow up inspection comments and corrective action will be listed as "Follow up Inspection:" to inspection clarity.	stjohnw	07/26/2023
At time of inspection the well access two track and well location do not reflect any recent use or activity. Inspector found no evidence or indications that corrective action requirements from previous inspection have been completed.		

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403477349	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195777">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195777</a>
698600811	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195776">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195776</a>