

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2023

Submitted Date:

07/26/2023

Document Number:

698600805

FIELD INSPECTION FORMLoc ID 314033 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

22 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	
Chambers, Kit		Kchambers@ravenwoodlabs.com	
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Supervisor
, Engineering		dnr_cogccengineering@state.co.us	
, Enforcement		dnr_cogccenforcement@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	Eastern Environmental Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290483	WELL	PR	12/01/2020	GW	095-06122	GARRETT 8-33-6-45	PR

General Comment:

Follow up Inspection completed as required for FIR Document Number 701303070 dated 04/12/2023.

Location				
Lease Road:				
Type	Access			
comment:	Two track off maintained county road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Well sign located on Meter Shed door at well location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	<p>EMERGENCY CONTACT NUMBER LIST ON SIGNAGE (877) 425-4882: RECEIVED AUTOMATED NOTIFICATION MESSAGE THAT THE NUMBER IS NOT IN SERVICE / UNASSIGNED.</p> <p>Follow up Inspection: Emergency contact #877-425-4882 posted on well sign message when called states disconnected or no longer in service.</p>			
Corrective Action:	<p>COMPLY WITH RULE 600 SERIES</p> <p>Corrective Action Date remains the same to document noncompliance.</p>			Date: 05/10/2023
Good Housekeeping:				
Type	DEBRIS			
Comment:	Remove fence Post and cribbing plank not in use at well location.			
Corrective Action:	Comply with Rule 606			Date: 08/11/2023
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	<p>REMOVE/REMEDiate/DISPOSE/BACKFILL STAINED/SATURATED SOILS AND HOLES AT WELLHEAD</p> <p>Follow up Inspection: Impacted soils remain at thw wellhead. No visible indication of clean up or remediation.</p>			
Corrective Action:	<p>COMPLY WITH RULE 900 SERIES</p> <p>Corrective Action Date remains the same to document noncompliance.</p>			Date: 04/13/2023
Lube Oil	Pump Jack			
Comment:	Remove/Remediate/Dispose of accumulated deposit of lube oil on Pump Jack Pad and surrounding impacted soils.			
Corrective Action:	Comply with Rule 906			Date: 07/28/2023
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Stock panel fencing around surface equipment at well location.			

Corrective Action:		Date:
Equipment:		corrective date
Type: Ancillary equipment	# 1	
Comment: Wellhead. Rods and tubing in wellbore. Tubing valve closed. Casing valve closed.		
Corrective Action:		Date:
Type: Prime Mover	# 0	
Comment: Removed.		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: GAS METER CALIBRATION - METER NOT CALIBRATED ANNUALLY - NO SIGNATURE CARD PRESENT IN MR SHED Follow up Inspection: Chart in Meter Box dated 12-1-22. Meter Calibration/Test Lod dated 7-14-20.		
Corrective Action: CALIBRATE GAS METERING EQUIPMENT ANNUALLY TO COMPLY WITH RULE 430.d(1) Corrective Action Date remains the same to document noncompliance.		Date: 05/11/2023
Type: Other	# 1	
Comment: Steel Meter Shed.		
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment: Concrete pad (Pump Jack).		
Corrective Action:		Date:
Type: Pump Jack	# 0	
Comment: Removed.		
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290483	Type:	WELL	API Number:	095-06122	Status:	PR	Insp. Status:	PR
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Rods and tubing in wellbore. Casing valve closed. Tubing valve closed. Well appears to be Shut In as reported 8/1/2022. Gas meter chart in meter box at time of inspection is dated 12-1-22. Review of electronic well file reflects last reported production status is 8/1/2022.</div>									
Corrective Action: <div>Submit required Form 7(s) to COGCC per rule 413.</div> Date: 08/29/2023									

Environmental			
Spills/Releases:			
Type of Spill: NON E&P WASTE		Estimated Spill Volume:	
Comment: Remove/Remediate/Dispose of accumulated deposit of lube oil on Pump Jack Pad and surrounding impacted soils.			
Corrective Action: Comply with Rule 906		Date: 07/28/2023	
Reportable:		GPS: Lat	Long
Proximity to Surface Water:		Depth to Ground Water:	
Water Well Complaint:			
DWR Receipt Num:		Owner Name:	GPS : Lat Long
Field Parameters:			
Sample Location:		Comment:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Original comments and corrective action for FIR document #701603070 are in all capital spelling. Follow up inspection comments and corrective action will be listed as "Follow up Inspection:" to aid in inspection clarity.	stjohnw	07/26/2023
At time of inspection the well access two track and well location do not reflect any recent use or activity. Inspector found no evidence or indications that corrective action requirements from previous inspection have been completed.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403478002	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6196469
698600816	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6196468