

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2023

Submitted Date:

08/15/2023

Document Number:

699107202

FIELD INSPECTION FORM

Loc ID 318843 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| , | | rbucogccinspectionreports@chevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|------------------------------------|-------------|
| 318843 | LOCATION | AC | | | - | CHAMPLIN 246 AMOCO A-62N64W 27SESW | AC |

General Comment:

[This is an inspection on the tank battery](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---------|-------|--|
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------|-------|--|
| Comment: | Adequate | Date: | |
| Corrective Action: | | | |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | WEEDS | | |
| Comment: | Overgrown vegetation growing in and around the tank battery needs to be removed for good housekeeping. See attached photos. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 08/25/2023 |

Overall Good:

Spills:

| Type | Area | Volume | |
|------|------|--------|--|
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

Equipment:

| Type: | | | corrective date |
|-----------------------------|-----|-------|-----------------|
| Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Tanks and Berms: | | | | | |
|-------------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.105700,-104.542100 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Inspected Facilities

Facility ID: 318843 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>ECMC Inspection Report Summary On Tuesday 8/15/23 at approximately 0845hrs I, Inspector Adam Burns, Conducted an on-site inspection at Champlin 246 Amoco A-62N64W 27SESW Tank Battery of Chevron. Location ID #318843 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Overgrown vegetation in and around the tank battery, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 8/25/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p> | burnsa | 08/15/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 699107203 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6219832 |