

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2023

Submitted Date:

08/10/2023

Document Number:

698600902

FIELD INSPECTION FORMLoc ID 336866 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

23 Number of Comments

9 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Pesicka, Conor		conor.pesicka@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280166	WELL	PR	12/01/2021	GW	125-09513	BOWMAN 9-21-5-44	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained county road. Two track has not been maintained.		
Corrective Action:	Repair and maintain lease road to comply with rule 603.I.	Date:	09/10/2023

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign at well location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service.

Corrective Action: Install sign to comply with Rule 605.a.

Date: 09/10/2023

Good Housekeeping:

Type	WEEDS		
Comment:	Well location has vegetation growing inside fencing.		
Corrective Action:	Comply with Rule 606.	Date:	08/18/2023
Type	DEBRIS		
Comment:	Production related debris left inside wellhead fencing.		
Corrective Action:	Comply with Rule 606.	Date:	08/26/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	WELLHEAD		
Comment:	Stock Panel Fencing around surface equipment at well location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Meter Run. Chart in Meter Box dated 11-30-22. Meter Calibration/Test Log dated 8-25-20. Well Inlet Valve open. Gas Outlet Valve open. Water Outlet valve closed.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	09/10/2023
Type: Ancillary equipment	# 1		

Comment:	Wellhead. Rods removed. Tubing in wellbore. Tubing valve closed, not connected. Tubing valve leaking out of open end, not sealing and unplugged. Casing valve closed. Wellhead is leaking at the cap and packing.			
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date:	08/09/2023
Type: Deadman # & Marked	# 2			
Comment:	Located 2 Deadmen with markers down. Unable to locate remaining Deadmen.			
Corrective Action:			Date:	
Type: Prime Mover	# 0			
Comment:	Removed.			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Metal Meter Shed.			
Corrective Action:			Date:	
Type: Bradenhead	# 0			
Comment:	Bradenhead inaccessible or not visible.			
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date:	08/21/2023

Venting:

Yes/No	YES		
Comment:	Tubing valve not connected and not sealing. Valve is releasing gas from the open ended valve. Wellhead is leaking gas from the Wellhead Cap between the tubing and packing.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).	Date:	08/09/2023

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 280166 Type: WELL API Number: 125-09513 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Pump Jack removed. Rods have been removed from the wellbore. Tubing appears to be in the wellbore. Tubing valve is closed and not connected (Leaking out of unplugged open end). Casing valve closed. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open, Water outlet valve closed. Wellhead is leaking at the cap.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Based on current valve settings at the wellhead the well is SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/10/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403492694	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6214193
698600917	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6214188
698600918	Wellhead Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6214189