

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/10/2023

Submitted Date:

08/10/2023

Document Number:

699107166

**FIELD INSPECTION FORM**

Loc ID 317921 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10528  
Name of Operator: ARCH OIL & GAS LLC  
Address: 16400 DALLAS PARKWAY SUITE 305  
City: DALLAS State: TX Zip: 75248

**Findings:**

- 14 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
HEASLIP, TRACY	(239) 404-0929	theaslip@archog.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
317921	LOCATION	AC			-	CUYKENDALL-LAUCK-62N63W 18SEW	AC

**General Comment:**

[This is an inspection on the tank battery](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Pit needs a capacity label. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/22/2023
Type	TANK LABELS/PLACARDS		
Comment:	Pit needs a new nfpa placard due to the one being weathered. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	09/22/2023
Type	BATTERY		
Comment:	Battery sign doesnt reflect current operator. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	09/22/2023

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment next to gas meter run, needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023
Type	WEEDS		
Comment:	Overgrown vegetation around the location, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	09/22/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	IGNITOR/COMBUSTOR		
Comment:	barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barbwire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	did not check meter card due to overgrown vegetation.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV FIBERGLASS		40.139700,-104.481300
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	n/a
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Pit berm appears to be weathered and needs maintained. See attached photo.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 09/22/2023

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.139300,-104.481400
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 317921 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Thursday 8/10/23 at approximately 0730hrs I, Inspector Adam Burns, Conducted an on-site inspection at CUYKENDALL-LAUCK -62N63W 18SEW Tank Battery of Arch Oil &amp; Gas LLC.                      Location ID# 317921 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Well sign does not reflect current operator. Install sign to comply with Rule 605.g. With a Corrective Action date of 9/22/23                      Pit needs a capacity label. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23                      Pit needs a new nfpa placard due to the one being weathered. Install sign to comply with Rule 605.g. With a Corrective Action date of 9/22/23                      Unused equipment next to gas meter run, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23                      Overgrown vegetation around the location, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23                      Pit berm appears to be weathered and needs maintained. Repair or install berms or other secondary containment devices per Rule 603.o. With a Corrective Action date of 9/22/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	08/10/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403493659	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215242">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215242</a>
699107167	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215226">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215226</a>