

# Inspection Photos

API: 061-06166

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 8/24/2023



## Inspection Photos



**Photo 1.** Facing southwest toward the location. The cattlegurd entering the location is filled in with sediment and needs to be maintained.





## Inspection Photos



**Photo 2.** The secondary containment at the tank is insufficient to contain a spill.





## Inspection Photos

Aug 24, 2023 at 12:39:15 PM



**Photo 3.** Facing toward the well. There was a gas hissing noise heard from the wellhead and a hydrocarbon odor was present. Operator was immediately notified.



## Inspection Photos



**Photo 4.** Facing northwest toward the location. The fence around the location is in disrepair. There are unused areas of the location that should be reclaimed.

