

# Inspection Photos

API: 061-06271

Operator: SAMSON OIL COMPANY

Inspection Date: 8/24/2023



## Inspection Photos



**Photo 1.** Drone aerial photo facing west toward the location.



## Inspection Photos



**Photo 2.** Drone aerial photo facing west down toward the location. The reddish brown vegetation is undesirable weeds (Kochia). The desirable vegetation has not re-established and there are bare areas with no vegetation.



## Inspection Photos



**Photo 3.** Drone aerial photo facing east down toward the location. The reddish brown vegetation is undesirable weeds (Kochia). The desirable vegetation has not re-established and there are bare areas with no vegetation. The bare area appears to be impacted soil from the well site.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 061-06271 | Date: 8/24/2023


## Inspection Photos



**Photo 4.** Drone aerial photo facing south toward the location. The reddish brown vegetation is undesirable weeds (Kochia). The desirable vegetation has not re-established and there are bare areas with no vegetation.



## Inspection Photos



**Photo 5.** Closer view of the location facing west. The tall undesirable weeds (Kochia) which needs to be controlled.



## Inspection Photos



**Photo 6.** Closer view of the location facing south. The tall undesirable weeds (Kochia) which needs to be controlled.

