

Inspection Photos

API: 061-06366

Operator: SAMSON OIL COMPANY

Inspection Date: 8/24/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing south toward the former access road and location. The perennial vegetation along the access road has re-established.



Inspection Photos



Photo 2. Drone aerial photo facing south toward the location. The green and reddish vegetation is undesirable weeds (Kochia) The desirable vegetation has not re-established.



Inspection Photos



Photo 3. Drone aerial photo facing north toward the location. The green and reddish vegetation is undesirable weeds (Kochia) The desirable vegetation has not re-established.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06366 | Date: 8/24/2023

Inspection Photos



Photo 4. Closer view of the location and tall undesirable weeds (Kochia) which needs to be controlled. The fence installed does not completely surround the entire location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-06366 | Date: 8/24/2023