

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2023

Submitted Date:

08/18/2023

Document Number:

701103802

**FIELD INSPECTION FORM**

Loc ID 323893 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Morgan, John		john.morgan@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159398	UIC DISPOSAL	AC	09/25/2012		-	604-1 SWD	EG

**General Comment:**

Flowline integrity inspection:  
Unused equipment (flowlines)  
Storm water damage of location berm.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	6-4" unused flowlines on west edge of location. 4 of the lines run off the north end of location with 2 lines ending at location Cascade Creek/697-04D loction id # 462936 and the 2 others continue west passing thru location CC/0605-02 Pad location id# 323998 and ending of the east edge of location Cascade Creek/697-05C location id# 421340. 2 other lines leave from the south end of location and run along the north edge of location Cascade Creek/608-41 location id # 324100 and end of the east edge of location Cascade Creek/697-08A location id # 424797. 1 - 6" unused poly line on the edge of location. 1-3" Open ended poly pipe sticking up inside of yellow barricade south of location.		
Corrective Action:	Comply with Rule 606 Ensure flowline(s) are isolated and depressurized; associated wells and isolation valves are SI/ OOSLAT to prevent unintentional release per 1102.j.7 Identify and report flowlines status, purpose and where the lines end at. Work with CECMC Flowline Integrity group to Abandon flowlines in accordance of Rule 1105	Date:	09/30/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 159398 Type: UIC API Number: - Status: AC Insp. Status: EG

**Flowline**

#1	Type:	6 of Lines	
----	-------	------------	--

Flowline Description

Flowline Type: \_\_\_\_\_ Size: 4" Material: Carbon Steel  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: 6- 4" flowlines leaving location. 4 are leaving the north west corner of location and 2 are leaving the south west corner of location. 1 of the south flowlines is open ended, the plug is on the ground near the line.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#2	Type:	1 of Lines	
----	-------	------------	--

Flowline Description

Flowline Type: \_\_\_\_\_ Size: 3" Material: Poly  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: Open ended poly pipe sticking up inside of yellow barricade south of location.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: [Breach of berm and erosion of hillside along the west edge of location.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 09/16/2023

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403518666	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239816">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239816</a>
701103803	Flowline integrity inspection 701103802 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239810">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239810</a>
701103804	Map of unused flowlines	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239811">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239811</a>