

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2023

Submitted Date:

09/13/2023

Document Number:

697008022

**FIELD INSPECTION FORM**Loc ID 431642 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment |
|--------------|-------|--------------------------|---------|
| ,            |       | cogccinspection@pdce.com |         |

**Inspected Facilities:**

| Facility ID | Type         | Status | Status Date | Well Class | API Num | Facility Name                  | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|--------------------------------|-------------|
| 442936      | TANK BATTERY | AC     | 08/21/2015  |            | -       | Tailholt FD Tank Battery 11-2D | AC          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | TANK LABELS/PLACARDS                                |       |            |
| Comment:           | Crude oil tanks lack placards, see attached photos. |       |            |
| Corrective Action: | Install sign to comply with Rule 605.h.             | Date: | 10/16/2023 |
| Type               | BATTERY   |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |
| Type               | OTHER   |       |            |
| Comment:           | Lease road entrance                                 |       |            |
| Corrective Action: |   | Date: |            |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | TRASH                                       |       |            |
| Comment:           | Trash behind meter run, see attached photo. |       |            |
| Corrective Action: | Comply with Rule 606.                       | Date: | 10/16/2023 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |                          |       |  |
|--------------------|--------------------------|-------|--|
| Type               | OTHER                    |       |  |
| Comment:           | Soundwall at compressors |       |  |
| Corrective Action: |                          | Date: |  |

**Equipment:**

|                       |      |       |                 |
|-----------------------|------|-------|-----------------|
|                       |      |       | corrective date |
| Type: Bird Protectors | # 12 |       |                 |
| Comment:              |      |       |                 |
| Corrective Action:    |      | Date: |                 |
| Type: Compressor      | # 2  |       |                 |
| Comment:              |      |       |                 |
| Corrective Action:    |      | Date: |                 |
| Type: Gathering Line  | # 1  |       |                 |
| Comment:              |      |       |                 |
| Corrective Action:    |      | Date: |                 |

|                                   |   |       |            |
|-----------------------------------|---|-------|------------|
| Type: Prime Mover                 | # 2   |       |            |
| Comment:                          | Electric motors on LACT   |       |            |
| Corrective Action:                |   | Date: |            |
| Type: LACT                        | # 1   |       |            |
| Comment:                          |   |       |            |
| Corrective Action:                |   | Date: |            |
| Type: Ancillary equipment         | #   |       |            |
| Comment:                          | Bulk lube oil storage wildlife netting requires reinstallation, see attached photo.   |       |            |
| Corrective Action:                | Install or repair wildlife protection equipment.  | Date: | 10/16/2023 |
| Type: Horizontal Heated Separator | # 6   |       |            |
| Comment:                          |   |       |            |
| Corrective Action:                |   | Date: |            |
| Type: Emission Control Device     | # 6   |       |            |
| Comment:                          | Pilots are on   |       |            |
| Corrective Action:                |   | Date: |            |
| Type: Gas Meter Run               | # 1   |       |            |
| Comment:                          | Calibration card is current   |       |            |
| Corrective Action:                |   | Date: |            |
| Type: Prime Mover                 | # 2   |       |            |
| Comment:                          | Natural gas engines on compressors  |       |            |
| Corrective Action:                |   | Date: |            |
| Type: Ancillary equipment         | #   |       |            |
| Comment:                          | Automation array, solar array, methanol sytem in secondary containment, bulk lube oil storage in secondary containment, telemetry array |       |            |
| Corrective Action:                |   | Date: |            |

**Tanks and Berms:**

| Contents           | #        | Capacity | Type           | Tank ID | SE GPS |
|--------------------|----------|----------|----------------|---------|--------|
| PRODUCED WATER     | 4        | OTHER    | PBV FIBERGLASS |         | ,      |
| Comment:           | 150 bbls |          |                |         |        |
| Corrective Action: |          | Date:    |                |         |        |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

Inspector Name: Peterson, Tom

|                    |          |                     |                     |             |        |       |
|--------------------|----------|---------------------|---------------------|-------------|--------|-------|
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |       |
| CRUDE OIL          | 15       | 400 BBLs            | STEEL AST           |             | ,      |       |
| Comment:           |          |                     |                     |             |        |       |
| Corrective Action: |          |                     |                     |             |        | Date: |
| <u>Paint</u>       |          |                     |                     |             |        |       |
| Condition          | Adequate |                     |                     |             |        |       |
| Other (Content)    |          |                     |                     |             |        |       |
| Other (Capacity)   |          |                     |                     |             |        |       |
| Other (Type)       |          |                     |                     |             |        |       |
| <u>Berms</u>       |          |                     |                     |             |        |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |       |
| Comment:           |          |                     |                     |             |        |       |
| Corrective Action: |          |                     |                     |             |        | Date: |
| <u>Venting:</u>    |          |                     |                     |             |        |       |
| Yes/No             | NO       |                     |                     |             |        |       |
| Comment:           |          |                     |                     |             |        |       |
| Corrective Action: |          |                     |                     |             |        | Date: |
| <u>Flaring:</u>    |          |                     |                     |             |        |       |
| Type               |          |                     |                     |             |        |       |
| Comment:           |          |                     |                     |             |        |       |
| Corrective Action: |          |                     |                     |             |        | Date: |



**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs   | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|-----------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  | Self Inspection | Pass                     |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User      | Date       |
|--|-----------|------------|
| <p><b>COGCC Inspection Report Summary</b></p> <p>On Wednesday 9/13/2023 at approximately 14:30 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Tailholt FD Tank Battery11-2D location #442936 in Weld County, Colorado.</p> <p>While there, I observed trash on location, the crude oil tanks lacked placards, and the bulk lube oil storage wildlife netting needed to be reinstalled. The following possible compliance issues were observed: Rule 605.h. with a corrective action date of 10/16/2023, Rule 606. with a corrective action date of 10/16/2023, Rule 902.b. with a corrective action date of 10/16/2023.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | petersont | 09/13/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403529193    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6249975">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6249975</a> |
| 697008023    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6249962">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6249962</a> |