

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/29/2023

Submitted Date:

09/29/2023

Document Number:

712700686

FIELD INSPECTION FORM

Loc ID 306897 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275013	WELL	PR	07/01/2019	CBM	067-08997	GEARHART C 2	PR

General Comment:

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Locked gate, 2C40 key.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume labels, NFPA placard.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Labels on chemical container.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on wellhead sign.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Chemical container disconnected from wellhead.		
Corrective Action:	Return to service or remove if no longer needed for ongoing operations per Rule 606.	Date:	10/13/2023
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panel enclosure around separator, tank, telemetry, and meterhouse.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel enclosure.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	T-post and barbed wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	3" line from wellhead to separator.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	3" line from separator to meterhouse. Calibration date 5/5/2023.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical service meter and transformer.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.226490,-107.664810	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 275013 Type: WELL API Number: 067-08997 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403546478	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6269578
712700691	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6269567