

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2023

Submitted Date:

09/22/2023

Document Number:

701007374

FIELD INSPECTION FORMLoc ID 414589 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 20165 NORTH 67TH AVENUE 122A

City: GLENDALE State: AZ Zip: 85308

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heffner, Taylor	(303) 219-3362	theffner@phxresources.com	
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414591	WELL	SI	04/01/2022	OW	073-06393	MOSHER 1-1H	SI

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign by cattle guard		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Pieces of concrete and wood south of control panel needs removed. Wires from control panel are exposed and need to be removed		
Corrective Action:	Comply with Rule 606	Date:	10/21/2023

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	6 cylinder Minneapolis Moline		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Vulcan 640		
Corrective Action:		Date:	
Type: Ancillary equipment	# 7		
Comment:	Gas scrubber, solar powered cathodic rectifier, control panel, phase convertor, telemetry equipment at control panel, electric circ pump and filter pot		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	FWKO on west side of treater		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:	Treater on north side of tank battery		
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:	Flare on east side of location. 3" produced gas valve is open at time of inspection		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		38.937760,-103.388020
Comment:	2-North tanks are oil				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLs	STEEL AST		38.937760,-103.388020
Comment:	South tanks (AGT 1, AGT 2, AGT 4) are produced water. Tanks are still plumbed into production. ALL water tanks have holes and need repaired or replaced				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 10/21/2023

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 414591	Type: WELL	API Number: 073-06393	Status: SI	Insp. Status: SI
Producing Well				
Comment:	Well is SI at time of inspection			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403545293	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6268360
701007384	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6268338