

# Inspection Photos

Loc: 324498

Operator: **OXY USA INC**

Inspection Date: 10/11/2023

County: Huerfano



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest along the access road near the SMU #1-12-B . This area was bladed and sediment was pushed further out creating disturbance. Grading activities as the only BMP is not sufficient to stabilize the road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324498 | Date: 10/11/2023

## Inspection Photos



**Photo 2.** Facing southwest along the access road. The road has recently been graded however, no other BMP's have been installed.



## Inspection Photos



**Photo 3.** Facing northeast back down the access road. Grading activities as the only BMP is not sufficient to stabilize the road and prevent stowmwater erosion issues of the road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324498 | Date: 10/11/2023

## Inspection Photos



**Photo 4.** Facing southwest along the access road. Grading of the road stopped at this point and the remainder of the road remains eroded with insufficient BMP maintenance.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324498 | Date: 10/11/2023

## Inspection Photos



**Photo 5.** Facing southwest further along the access road. There are areas of erosion occurring which need to be repaired and stabilized.



## Inspection Photos



**Photo 7.** Facing southwest further along the access road. There are areas of erosion occurring which need to be repaired and stabilized. Previous corrective action has not been completed.

Photo taken from previous inspection 6/1/2023.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324498 | Date: 10/11/2023

## Inspection Photos



**Photo 8.** Facing southwest further along the access road. There are areas of erosion occurring which need to be repaired and stabilized. Previous corrective action has not been completed.

Photo taken from previous inspection 6/1/2023.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324498 | Date: 10/11/2023