

# Interim and Stormwater Inspection

October 9, 2023

Operator: Investment Equip. LLC, #10330

Location ID: 319633

Inspection Document #:709400521

Adams county, CO

NWNE, Section 22, 2S 57W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos

Location Name: Clifford Causey #20

Location ID: 319633



Photo 1. Photo taken facing west, of wellhead location sign.

Inspection Photos

Location Name: Clifford Causey #20

Location ID: 319633

Oct 9, 2023 at 12:51:07 PM  
Fort Morgan CO 80701  
United States



**Photo 2. Photo taken facing west of well head.**

Oct 9, 2023 at 12:51:09 PM  
Fort Morgan CO 80701  
United States



**Photo 3. Photo taken facing west of perennial grasses and weeds (kochia) on working pad perimeter and in reclaimed area.  
Inspection**



Inspection Photos

Location Name: Clifford Causey #20

Location ID: 319633



**Photo 4. Photo taken facing east of weeds (kochia) on working pad perimeter.**



**Photo 5. Photo taken facing north, of weed (kochia) on working pad perimeter and in reclaimed area.**

Inspection Photos  
Location Name: Clifford Causey #20  
Location ID: 319633

Sep 7, 2023 at 3:23:42 PM



Photo 6. Photo taken facing east, of perennial grasses outside of reclaimed area, for reference vegetation.

Sep 7, 2023 at 2:58:50 PM  
Fort Morgan CO 80701  
United States



Photo 7. Photo taken of location sign.  
Tank battery ID 319632.

Inspection Photos

Location Name: Clifford Causey #20

Location ID: 319633

Sep 7, 2023 at 2:59:04 PM  
Fort Morgan CO 80701  
United States



**Photo 8.** Photo taken of battery, facing south. This is an off location tank battery.

Sep 7, 2023 at 3:01:10 PM  
Fort Morgan CO 80701  
United States



**Photo 9.** Photo taken facing north of vegetation and weeds (kochia & russian thistle) between tank battery and pits on location.

Inspection Photos  
Location Name: Clifford Causey #20  
Location ID: 319633



**Photo 11. Photo taken facing north, of large gully with exposed un-stabilized flowlines**



**Photo 11. Photo taken facing southwest, of perennial grasses outside of reclaimed area, for reference vegetation**