

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2023

Submitted Date:

10/17/2023

Document Number:

713600302

**FIELD INSPECTION FORM**

Loc ID 324498 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 66561  
Name of Operator: OXY USA INC  
Address: PO BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
NEVVILLE TONI		toni_newville@oxy.com	
OXY		COGCCinspections@oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324498	LOCATION	AC			-	DIKE MOUNTAIN UNIT-628S70W 13SEW	RI

**General Comment:**

On 10/11/2023, Ryan Costa conducted a follow up of the previous inspection #690204292. Operator is directed to perform corrective actions outlined on this inspection report immediately. See attached photos and additional details within this report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	The access road is not maintained to allow safe vehicle access to the wellsite. There are areas of the road that are very steep with trees and large rocks fallen down along the road. Access roads must be maintained in in a stable condition to accommodate all weather access. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 603.I.	Date:	10/11/2023

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
	Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>

**Flaring:**

Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There has been grading of the access road performed since previous inspection but no other BMP's were installed. Grading activities as the only BMP is not sufficient to stabilize the road. BMP's along the steep road must be selected based off of site specific conditions and must be implemented in accordance with good engineering practice. Corrective action will remain out of compliance until completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403562644	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286581">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286581</a>
713600303	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286552">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286552</a>