

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403569215

Date Received:
10/25/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10665
Name of Operator: CCRP OPERATING INC
Address: 12136 W BAYAUD AVE STE 320
City: LAKEWOOD State: CO Zip: 80228

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Cody Duran	303-880-0790	cduran@rockiesresourcesllc.com
Jon Anderson	970-373-7397	janderson@rockiesresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504895
Inspection Date: 10/11/2023 FIR Submit Date: 10/17/2023 FIR Status:

Inspected Operator Information:

Company Name: CCRP OPERATING INC Company Number: 10665
Address: 12136 W BAYAUD AVE STE 320
City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: 442375

Location Name: Cox Number: 22-B Pad County:
Qtrqr: NENW Sec: 22 Twp: 12N Range: 64W Meridian: 6
Latitude: 40.998623 Longitude: -104.535017

FACILITY - API Number: 05-123-00 Facility ID: 442375

Facility Name: Cox Number: 22-B Pad
Qtrqr: NENW Sec: 22 Twp: 12N Range: 64W Meridian: 6
Latitude: 40.998623 Longitude: -104.535017

CORRECTIVE ACTIONS:

1 CA# 185302

Corrective Action: Control and contain spills/releases, conduct maintenance on equipment and clean up per Rule 912.a.

Date: 10/11/2023

The corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED Date of Completion: 10/24/2023

Wellhead stained dirt was removed 10/19. Contaminated containment gravel was removed and replaced 10/24.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 185303

Corrective Action: Comply with Rule 606.a.

Date: 10/11/2023

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/19/2023

Operator
Comment:

Load out hoses removed and placed outside containment.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Contaminated soil under wellhead was removed and replaced on 10/19. Load out hoses were disconnected and placed outside secondary containment. Removal of contaminated material inside containment commenced on 10/24.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cody Duran

Signed:

Title: Production Engineer

Date: 10/25/2023 2:23:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403569407	Cox 5 wellhead after photo 10/19
403572842	Capped load out line
403572846	Cox 22 pad containment after photo
403572848	load out line outside containment and capped

Total Attach: 4 Files