

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2023

Submitted Date:

10/20/2023

Document Number:

695108689

FIELD INSPECTION FORM

Loc ID 308452 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|-------------------|---------------------------------|
| WARD, GIENA | | gward@ogrisop.com | All Inspections |
| BACA, DAVE | 719-859-4066 | dbaca@ogrisop.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 272343 | WELL | PR | 08/28/2009 | CBM | 071-08062 | HILL RANCH 32-8 | PR |
| 292527 | PIT | | 09/30/2007 | | - | HILL RANCH 32-08 | |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | |
|--------------------|--|
| Type | OTHER |
| Comment: | PHOTO 4: Signs of recent slow leak from wellhead. Salt/mineral buildup is evident on the wellhead and ground around wellhead. |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals, remove salt/mineral buildup, maintain in good mechanical condition remove and dispose of impacted material per Rule 608.e. |

Date: 11/20/2023

Overall Good:

Spills:

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | Count | Comment | Corrective Action | Date | corrective date |
|---------------------------|-------|--|-------------------|-------|-----------------|
| Type: Deadman # & Marked | # 5 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | | | |
| | | Comment: is accessible | | | |
| | | Corrective Action: | | Date: | |
| Type: Progressive Cavity | # 1 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | | | |
| | | Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. | | | |
| | | Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | | | |
| | | Comment: | | | |
| | | Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 272343 Type: WELL API Number: 071-08062 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/19/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 292527 Type: PIT API Number: - Status: Insp. Status:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: PHOTO 5: OILY WASTE IN ENGINE SKID. COMPLY WITH RULE 1002.f.(2)B,

Corrective Action: Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 10/23/2023

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 292527 Lat: 37.042050 Long: -104.903500

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403568058 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6293037 |
| 695108733 | insp. photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6293030 |